

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD	Ref:	CS3/ASM21004304/Qtce2	
	8 SHENTON WAY TOWERSINGAPOR	-	Date:	19/04/2021	
	ATTN: YU DOMINIO	CYISHAN	Code	: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 1154Y	Veh. Inspected	SLJ 1623B	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03704	Excess (\$)	0.00	
	Assign From	YU DOMINIC YISHAN	Assign Date	05/04/2021	
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA ROADSTER RHT 2.0 A	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	NCEC202125	Colour	BLUE	
	Odometer	157412 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55Z R16	KUMHO	6 mm	
	L/H Front Tyre	205/55Z R16	KUMHO	6 mm	
	R/H Rear Tyre	205/55Z R16	KUMHO	6 mm	
	L/H Rear Tyre	205/55Z R16	KUMHO	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
5.	General Information				
	Accident Date	31/03/2021	Inspect Date / Time	08/04/2021 (11:30 AM)	
_	Survey held at	ANN JOO MOTOR PL			
	BLK 176 SIN MING DRIVE #01-17 SIN MING AUTOCARE SINGAPORE 575721				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21004304/Qtce2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser