

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: CS/AGI21004308/Dqf3n2		
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 23/12/2021		
			Co	ode: AGI		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKU 1374Z	Veh. Inspected	SHC 8825Z		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	C10009654/JM	Excess (\$)	0.00		
	Assign From	IVY RATILLA	Assign Date	05/04/2021		
2.	2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI 140	C.C	1685		
	Engine No.	HIDDEN	Year of Reg.	2015		
	Chassis No.	KMHLB41UMGU082941	Colour	BLUE		
	Odometer	962395 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	NIL		
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	205/60 R16	WEST LAKE	5 mm		
	L/H Front Tyre	205/60 R16	WEST LAKE	5 mm		
	R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm		
	L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm		
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	01/04/2021	Inspection Date	06/04/2021		
	Survey held at	BIFROST AUTO PTE LTD				
		8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: