

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004309/APA3Q2**Date:** 14/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700040598
Claimant Vehicle No :	SMQ2631Y	Insured Vehicle No :	SDF556J
Date of Loss:	01/04/2021	Nature of Claim:	TP
		Claim No:	4736512127SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ2631Y	Engine No:	2ZR2F81584
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU30J052313
Reg. Date:	06/11/2019 (Man. Year: 2019)	Odometer:	38770 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,686.71	7,398.12	22,288.59	75.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,040.00	1,730.00	3,310.00	65.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,726.71	9,128.12	25,598.59	73.71
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	34,726.71	7,500.00	27,226.71	78.40
+ GST 7.00/7.00% (S\$)	2,430.87	525.00	1,905.87	78.40
Nett Amount (S\$)	37,157.58	8,025.00	29,132.58	78.40
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,867.00		

INSPECTION

Date of Assignment:	05/04/2021	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883
Date Inspected:	05/04/2021 Inspected At:	
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	865.25 F	*576.00 FL
2	1		*FRONT BUMPER EMBLEM LOGO	Necessary	121.15 F	*72.00 FL
3	1		*FRONT BUMPER NUMBER PLATE	Bent	50.00 F	*50.00 FL
4	2		*FRONT BUMPER SIDE RETAINER	Necessary	343.56 F	*236.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	561.60 F	*- FL
6	1		*FRONT BUMPER REINFORCEMENT FOAM	Cracked	125.00 F	*125.00 FL
7	1		*FRONT BUMPER CENTER GRILLE	Cracked	561.90 F	*561.90 FL
8	8		*FRONT BUMPER CENTER GRILLE CLIP	Necessary	52.00 F	*20.00 FL
9	1		*FRONT BUMPER LOWER	Not Necessary	571.00 F	*- FL
10	1		*FRONT BUMPER LOWER GARNISH	Deformed	371.00 F	*371.00 FL
11	1		*FRONT BUMPER LOWER COVER	Not Necessary	98.00 F	*- FL
12	2		*FRONT BUMPER FOG LAMP	Not Necessary	1,462.20 F	*- FL
13	2		*FRONT BUMPER TOWING COVER	Not Necessary	242.20 F	*- FL
14	1		*FRONT SUPPORT PANEL	Not Necessary	1,712.45 F	*- FL
15	2		*FRONT SUPPORT PANEL AIR GUIDE	Not Necessary	130.00 F	*- FL
16	1		*FRONT CONDENSOR	Not Necessary	1,210.40 F	*- FL
17	1		*FRONT AIR-CON CONDENSER FAN MOTOR ASSY	Not Necessary	971.25 F	*- FL
18	1		*FRONT RADIATOR	Not Necessary	1,675.35 F	*- FL
19	1		*FRONT RADIATOR FAN MOTOR ASSY	Not Necessary	825.00 F	*- FL
20	1		*FRONT HEAD LAMP	Cracked	5,562.20 F	*2,625.00 FL
21	1		*FRONT HEAD LAMP LOWER BRACKET	Not Necessary	185.00 F	*- FL
22	1		*REAR BOOT LID	Repair	1,235.70 F	*- FL
23	2		*REAR BOOT LID HINGE	Not Necessary	548.00 F	*- FL
24	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	922.00 F	*- FL
25	1		*REAR BOOT LID EMBLEM LOGO	Necessary	125.00 F	*125.00 FL
26	1		*REAR BOOT LID PRIUS+LOGO	Necessary	124.00 F	*124.00 FL
27	1		*REAR BOOT LID HYBRID LOGO	Necessary	130.00 F	*130.00 FL
28	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
29	1		*REAR BOOT LID INNER LOCK	Not Necessary	361.00 F	*- FL
30	1		*REAR BOOT LID INNER WEATHERSTRIP	Crumpled	323.00 F	*323.00 FL
31	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	681.90 F	*- FL
32	10		*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	65.00 F	*- FL
33	1		*REAR BOOT LID WINDSCREEN SEAL	Not Necessary	105.00 F	*- FL
34	1		*REAR FENDER INNER TRIM BOARD (LH)	Cracked	638.90 F	*638.90 FL
35	1		*REAR FENDER INNER TRIM BOARD CLIP (16 PCS)	Necessary	104.00 F	*30.00 FL
36	1		*REAR BUMPER	Deformed	549.00 F	*549.00 FL
37	1		*REAR BUMPER LOWER LID	Deformed	726.00 F	*612.00 FL
38	1		*REAR BUMPER LOWER COVER	Torn	187.00 F	*187.00 FL
39	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
40	2		*REAR BUMPER SIDE RETAINER	Necessary	216.00 F	*216.00 FL
41	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	116.00 F	*- FL
42	1		*REAR BUMPER REVERSE SENSOR	Damaged	780.00 FS	*200.00 FS
43	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	360.00 F	*- FL
44	1		*REAR BUMPER REINFORCEMENT	Dented	625.00 F	*350.00 FL
45	1		*REAR END PANEL	Dented	896.00 F	*645.00 FL
46	1		*REAR END PANEL TOP GARNISH	Deformed	358.00 F	*292.00 FL
47	1		*REAR TOOL SPONGE	Cracked	385.50 F	*385.50 FL
48	0		*REAR TAIL LAMP	Not Necessary	978.00 F	-
49	2		*REAR TAIL LAMP LOWER BRACKET	Cracked	84.00 F	*84.00 FL
50	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*20.00 FL
51	2		*REAR BUMPER REINFORCEMENT BRACKET	Dented	219.20 F	*219.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)

29,686.71

9,797.50

- List Item Discount on L Items 0.00/25.00% (\$\$)

0.00

2,399.38

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (\$)	29,686.71	7,398.12
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR ,& TOP UP GAS	New	280.00	0.00
2	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	60.00
3	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
4	TO CHECK WIRING	New	80.00	60.00
5	TUFF KOTE	New	100.00	60.00
6	PANEL BEATING	New	2,200.00	700.00
7	SPRAY PAINTING	New	2,000.00	800.00
Gross Labour Cost (S\$)			5,040.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >