

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004312/T1RA3Q2
Date: 25/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070119913
Claimant Vehicle No :	SHA4271H	Insured Vehicle No :	SMU4588E
Date of Loss:	03/04/2021	Nature of Claim:	TP
		Claim No:	8019923270SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4271H		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDEU460315
Reg. Date:	12/05/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU088743
Colour:	Blue	Odometer:	775409 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,350.56	530.40	820.16	60.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	880.00	420.00	32.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,650.56	1,410.40	1,240.16	46.79
Approved Total (Overridden) (S\$)		1,150.00		

(S\$)	2,650.56	1,150.00	1,500.56	56.61
+ GST 7.00/7.00% (S\$)	185.54	80.50	105.04	56.61
Nett Amount (S\$)	2,836.10	1,230.50	1,605.60	56.61
+ Car Rental (3.0 x S\$110.67/day) (S\$)		332.01		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,564.51		

INSPECTION

Date of Assignment: 05/04/2021

Date Inspected: 06/04/2021

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER W LIP & FOG LAMP C	Repair	1,025.20 FL	*- FL
2	1		*PANEL -FEBNDER LH	Bent	663.00 FL	*663.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					1,688.20	663.00
- List Item Discount on L Items 20.00/20.00% (\$)					337.64	132.60
Total Parts (\$)					1,350.56	530.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	280.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	RENEW ADVERTISEMENT STICKER -FENDER	New	100.00	100.00
Gross Labour Cost (\$\$)			1,300.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >