

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Reg. No: 19960/198R GST Reg. No. 19-960/198-R                     |   |  |                 |      |                       |
|---|---|--|-----------------|------|-----------------------|
| Affiliated to Federation Internationale Des Experts En Automobile |   |  |                 |      |                       |
|   | AUTO & GENERA   | L INSURANCE (S) PL                                     | R               | Ref: | CS/AGI21004315/Aqf3n2 |
|   | (BUDGET DIRECT<br>190 CLEMENCEAI<br>SINGAPORE SHO<br>239924   | INSURANCE)<br>U AVENUE #03-01<br>PPING CENTRESINGAPORE | D               | ate: | 26/07/2021            |
|   |   |  | C               | ode: | AGI                   |
| 1. Policy Particulars :- THIRD PARTY CLAIM                        |   |  |                 |      |                       |
|   | Insured Veh.  | SGT 991B   | Veh. Inspected  |      | GW 8807H              |
|   | Policy No.  |  | Coverage (\$)   |      | 0.00                  |
|   | Claim No.   | C10009673/ST   | Excess (\$)     |      | 0.00                  |
|   | Assign From   | IVY RATILLA  | Assign Date     |      | 05/04/2021            |
| 2. Vehicle Particulars & Condition                                |   |  |                 |      |                       |
|   | Make & Model  | ISUZU TFR69H   | c.c             |      | 3059                  |
|   | Engine No.  | HIDDEN   | Year of Reg.    |      | 2003                  |
|   | Chassis No.   | JAATFR69H37100940                                      | Colour          |      | WHITE                 |
|   | Odometer  | 687683 KM  | Steering        |      | IN ORDER              |
|   | Brakes  | IN ORDER   | Modification    |      | STANDARD ALLOY RIM    |
|   | General   | GOOD   |                 |      |                       |
| 3. Conditions of Tyres  |   |  |                 |      |                       |
|   |   | Size   | Make            |      | Balance               |
|   | R/H Front Tyre  | 185 R14C   | ROVELO          |      | 6 mm                  |
|   | L/H Front Tyre  | 185 R14C   | ROVELO          |      | 6 mm                  |
|   | R/H Rear Tyre   | 185 R14C   | BRIDGESTONE     |      | 6 mm                  |
|   | L/H Rear Tyre   | 185 R14C   | BRIDGESTONE     |      | 6 mm                  |
| 4.  | Description of Damages  |  |                 |      |                       |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  |  |                 |      |                       |
|   | DAMAGES SEE DETAILS.  |  |                 |      |                       |
| 5.  | General Information   |  |                 |      |                       |
|   | Accident Date   | 02/04/2021   | Inspection Date |      | 06/04/2021            |
|   | Survey held at  | held at TWINCAR AUTOMOTIVE PTE LTD                     |                 |      |                       |
|   | 2 KAKI BUKIT AVE 2<br>#01-17 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921   |  |                 |      |                       |
| 5a.   | Remarks   |  |                 |      |                       |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |      |                       |
| 5b.   | Estimate Days of Repair   |  |                 |      |                       |

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: