

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S9M02011 Date: 29th April 2021

Our Ref: CS3/ASM19016111/Gtf3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Heng Xin Yi

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLL 3841P

INSURED VEHICLE: YP 6494M ACCIDENT DATE: 07/09/2019

We thank you for your instruction on 05/04/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLL 3841P from M/s Pro-option Services.
- b) Singapore Accident Statement of Vehicles SLL 3841P and YP 6494M.
- c) Final Repair Bill of SLL 3841P from M/s Paul Hoe Batteries & Motor Services.
- d) Colour damaged vehicle photographs of SLL 3841P.

Pre-Repair Inspection Date : 11/09/2019 at M/s Paul Hoe Batteries & Motor Services, Blk 1 Kaki Bukit Ave 6 #01-109 Autobay, Singapore 417833

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLL 3841P

Make & Model : Honda HRV 1.5 LX CVT

Year of Registration : 2017

Chassis Number : JHMRU1830GX201653

Engine Capacity : 1496 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.