

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004316/KRA3Q2
Date: 28/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700091587
Claimant Vehicle No :	SMC8228M	Insured Vehicle No :	SLV1702T
Date of Loss:	01/04/2021	Nature of Claim:	TP
		Claim No:	4463303484SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC8228M		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B5461697
Reg. Date:	21/06/2018 (Man. Year: 2018)	Chassis No:	GK81201446
Colour:	Metallic Dark Blue	Odometer:	77726 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,418.95	1,094.16	324.79	22.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	820.00	500.00	37.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,738.95	1,914.16	824.79	30.11
Approved Total (Overridden) (S\$)		1,500.00		

(S\$)	2,738.95	1,500.00	1,238.95	45.23
+ GST 7.00/7.00% (S\$)	191.73	105.00	86.73	45.24
Nett Amount (S\$)	2,930.68	1,605.00	1,325.68	45.23
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,912.45		

INSPECTION

Date of Assignment: 05/04/2021

Date Inspected: 14/04/2021 Inspected At: Autoclinic Pte Ltd (HQ)
 48 TOH GUAN ROAD EAST #02-136 ENTERPRISE HUB SINGAPORE 608586
 Singapore 608586

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT BUMPER	Buckled / Cut	1,230.50 FL	*1,020.20 FL
2	10		*FRONT BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
3	1		*FRONT RIGHT WHEEL	Dented	280.00 FS	*250.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	1,545.50
					- List Item Discount on L Items 10.00/20.00% (\$)	126.55
					Total Parts (\$)	1,418.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY AND SPRAY REPLACED PARTS (BUMPER+SIDE FENDER)	New	700.00	400.00
2	TO REMOVE DAMAGED PARTS ,PANEL BEATING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	500.00	360.00
3	TO REMOVE TYRE AND INSTALL BACK ,WHEEL BALANCING WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			1,320.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >