

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21004320/R1TCN2**Date:** 03/11/2021**REFERENCE**

Insured/Claimant:	LEE SWEE LING CHERYL	Policy No:	2100473850
Date of Loss:	31/03/2021	Nature of Claim:	OD Claim No: 3764746846SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT9574R	Engine No:	CJE100458
Make & Model:	AUDI A4, 1.8 TFSI (A)	Chassis No:	WAUZZZ8K6FA115080
Reg. Date:	26/06/2015 (Man. Year: 2015)	Odometer:	112119 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$62,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R16	Rear Tyre Size:	225/55R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,083.50	9,940.16	13,143.34	56.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	25,932.00	13,927.00	12,005.00	46.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	49,015.50	23,867.16	25,148.34	51.31
Approved Total (Overridden) (\$\$)		17,000.00		
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	48,215.50	16,200.00	32,015.50	66.40
+ GST 7.00/7.00% (\$\$)	3,375.09	1,134.00	2,241.09	66.40
Nett Amount (\$\$)	51,590.59	17,334.00	34,256.59	66.40

INSPECTION

Date of Assignment:	06/04/2021	24 BENOI SECTOR
Date Inspected:	05/04/2021 Inspected At:	SINGAPORE 629857
Estimated Period of Repair:	17.0 days	REPAIRER: PREMIUM AUTOMOBILES PTE LTD

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,451.00 FS	*1,960.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	228.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Scratched	267.00 FS	*213.20 FS
4	1		*REAR BUMPER CARRIER	Serviceable	681.00 FS	*- FS
5	2		*REAR BUMPER HOLDER BRACKET-LH/RH	Serviceable	446.00 FS	*- FS
6	2		*REAR BUMPER GUIDE SECTION-LH/RH	Serviceable	89.00 FS	*- FS
7	1		*REAR BUMPER UPPER GUIDE SECTION-LH/RH	N/s Cracked/O/s Not Necessary	47.00 FS	*18.56 FS
8	1		*REAR BUMPER PIN	Not Necessary	12.00 FS	*- FS
9	1		*REAR BUMPER SECURING STRIP	Serviceable	14.00 FS	*- FS
10	1		*REAR BUMPER PARKING AID SENSOR (3 Pcs)	Distorted (1 Pc only)	732.00 FS	*195.12 FS
11	1		*REAR BUMPER PARKING AID SENSOR SEAL	Necessary	6.00 FS	*4.16 FS
12	1		*REAR BUMPER WIRING SET	Serviceable	515.00 FS	*- FS
13	1		*REAR BOOT LID	Serviceable	3,361.00 FS	*- FS
14	1		*REAR BOOT LID ATTACHMENT PARTS	Serviceable	75.00 FS	*- FS
15	1		*REAR BOOT LID HINGE-LH/RJ	Serviceable	512.00 FS	*- FS
16	1		*REAR BOOT LID GASKET	Necessary	205.00 FS	*164.00 FS
17	1		*REAR BOOT LID ADHESIVE	Necessary	19.00 FS	*14.88 FS
18	1		*A4 EMBLEM	Necessary	99.00 FS	*79.04 FS
19	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
20	1		*TFSI EMBLEM	Necessary	99.00 FS	*79.04 FS
21	1		*REAR SIDE PANEL-LH	Buckled	4,003.00 FS	*2,915.20 FS
22	1		*REAR WINDOW	Not Necessary	1,128.00 FS	*- FS
23	1		*REAR SIDE WINDOW-LH	Necessary	305.00 FS	*243.60 FS
24	1		*PRIMER	Necessary	20.00 FS	*15.76 FS
25	1		*BOTTOM OUTER FLOOR PLATE-LH	Serviceable	403.00 FS	*- FS
26	1		*REAR SIDE PANEL CONNECTING PLATE-LH	Bent	340.00 FS	*271.60 FS
27	1		*REAR OUTER WHEEL HOUSING-LH	Serviceable	647.00 FS	*- FS
28	1		*REAR SIDE PANEL-LH	Bent	206.00 FS	*164.40 FS
29	1		*REAR WHEEL HOUSING LINER-LH	Cut	222.00 FS	*177.20 FS
30	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS-LH	Not Necessary	45.00 FS	*- FS
31	1		*REAR SIDE PANEL VENT TRIM	Distorted	72.00 FS	*57.52 FS
32	1		*OUTER TAIL LIGHT-LH	Broken	1,075.00 FS	*860.00 FS
33	1		*INNER TAIL LIGHT-LH	Scratched	901.00 FS	*720.80 FS
34	1		*REAR CROSS PANEL TRIM	Serviceable	189.00 FS	*- FS
35	1		*REAR BOOT COMPARTMENT TRIM-LH	Deformed	413.00 FS	*330.40 FS
36	1		*REAR BOOT COMPARTMENT FLOOR COVERING	Serviceable	708.00 FS	*- FS
37	1		*REAR BOOT LID TRIM	Serviceable	278.00 FS	*- FS
38	1		*REAR BOOT WARNING TRIANGLE RETAINER	Serviceable	58.00 FS	*- FS
39	1		*REAR BOOT WARNING TRIANGLE	Serviceable	193.00 FS	*- FS
40	1		*REAR DOOR SILL TRIM STRIP-LH	Serviceable	89.00 FS	*- FS
41	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
42	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
43	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
44	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
45	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
46	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
47	1		*SUNDRIES	Necessary	400.00 FS	*14.88 FS
48	1		*END PANEL (Supplementary)	Bent	312.50 FS	*250.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 23,083.50 9,940.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REINSTALL REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO REMOVE & TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM & WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO RENEW REAR WINDSCREEN & LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	600.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN & LHS 1/4 GLASS	New	400.00	0.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN & 1/4 GLASS	New	200.00	200.00
6	TO DISLODGE & REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE & RELAY TRAYS,ELECTRICAL & AUDIO EQUIPMENT.INSPECT FOR DAMAGE & RENEW WHERE NECESSARY	New	1,400.00	1,400.00
7	TO REMOVE & REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER & DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
9	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER	New	800.00	0.00
10	TO PUT THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	1,800.00	0.00
11	TO DISMANTLE & RENEW REAR BUMPER & REAR LID,TO CUT OUT & WELD LHS REAR FENDER,LHS CONNECTING PLATE,LHS BOTTOM PLATE & LHS INNER SIDE PANEL.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	9,100.00	4,500.00
12	TO RESPRAY REAR BUMPER,REAR LID,BOTH REAR FENDERS,LHS SILL PANEL,LHS CONNECTING PLATE,LHS BOTTOM PLATE,LHS INNER SIDE PANEL,DRAIN PANEL,ROOF CHANNEL,DOOR ENTRANCES & END PANELLING.TO CARRY OUT STONE CHIP TREATMENT,CAVITY PRESERVATION & JOINT SEALER WORKS	New	7,700.00	3,575.00
13	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
14	TO CUT OUT AND WELD REAR END PANEL	New	1,500.00	1,500.00
	Supplementary			
Gross Labour Cost (\$)			25,932.00	13,927.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >