

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21004323/EVCE2

Date: 14/05/2021

REFERENCE

Insured/Claimant: EUNICE BOH CHEK CHING Policy No: 1900085739
Date of Loss: 04/04/2021 Nature of Claim: OD Claim No: 0183124920SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML718X**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGJH722098
Reg. Date: 03/05/2019 (Man. Year: 2018) Chassis No: KNAF3416MK5031212
Colour: Blue Odometer: 23845 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$74,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Kumho 5 mm Rear Left Side: Kumho 5 mm
Front Right Side: Kumho 5 mm Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,893.20	4,433.60	1,459.60	24.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,900.00	4,910.00	990.00	16.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,793.20	9,343.60	2,449.60	20.77
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	11,193.20	8,743.60	2,449.60	21.88
+ GST 7.00/7.00% (S\$)	783.52	612.05	171.47	21.88
Nett Amount (S\$)	11,976.72	9,355.65	2,621.07	21.88

INSPECTION

Date of Assignment: 06/04/2021
Date Inspected: 05/04/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 13.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*PANEL ASSY-FRONT DOOR, LH	Dented	1,277.00 FL	*1,277.00 FL
3	1		*HINGE ASSY-FRONT DOOR, LH	Not Necessary	30.00 FL	*- FL
4	1		*HINGE ASSY-DOOR LOWER, LH	Not Necessart	27.00 FL	*- FL
5	1		*HANDLE ASSY-DOOR OUTSIDE, LH	Cut	164.00 FL	*164.00 FL
6	1		*COVER-FR DR O/S HDL LH	Not Necessary	14.00 FL	*- FL
7	1		*PAD-FR DR O/S HDL COVER, RH	Not Necessary	5.00 FL	*- FL
8	1		*PAD-FR DR O/S HDL HINGE, RH	Not Necessary	5.00 FL	*- FL
9	1		*BASE ASSY-FR DR O/S HANDLE LH	Not Necessary	52.00 FL	*- FL
10	1		*LATCH ASSY-FRONT DOOR, LH	Not Necessary	400.00 FL	*- FL
11	1		*STRIKER ASSY-DR	Not Necessary	14.00 FL	*- FL
12	1		*CHECKER ASSY-FRONT DOOR, LH	Not Necessary	44.00 FL	*- FL
13	1		*PANEL ASSY-FRONT DR MODULE, LH	Not Necessary	241.00 FL	*- FL
14	1		*MOTOR ASSY-FRONT POWER WDW, LH	Not Necessary	165.00 FL	*- FL
15	1		*PANEL ASSY-REAR DOOR, LH	Dented	1,377.00 FL	*1,377.00 FL
16	1		*HINGE ASSY-REAR DOOR UPPER, LH	Not Necessary	33.00 FL	*- FL
17	1		*HINGE ASSY-DOOR UPPER, LH	Not Necessary	26.00 FL	*- FL
18	1		*BASE ASSY-FR DR O/S HANDLE, LH	Not Necessary	52.00 FL	*- FL
19	1		*LATCH ASSY-REAR DOOR, LH	Not Necessary	309.00 FL	*- FL
20	1		*CHECKER ASSY-REAR DOOR, LH	Not Necessary	44.00 FL	*- FL
21	1		*PANEL ASSY-REAR DOOR MODULE, LH	Not Necessary	215.00 FL	*- FL
22	1		*MOTOR ASSY-POWER WDO REG RR, LH	Not Necessary	111.00 FL	*- FL
23	1		*BLACK TAPE-FR DR RR, LH	Necessary	13.00 FL	*13.00 FL
24	1		*BLACK TAPE-RR DR FR, LH	Necessary	13.00 FL	*13.00 FL
25	1		*BLACK TAPE-RR DR FRAME RR OTR	Necessary	8.00 FL	*8.00 FL
26	1		*PANEL-SIDE SILL OUTRER, LH	Dented	1,208.00 FL	*1,208.00 FL
27	1		*FILM-ANTI CHIPPG LH	Necessary	27.00 FL	*27.00 FL
28	1		*MOULDING ASSY-RR DR FRAME,LH (Supplementary)	Necessary	44.00 FL	*44.00 FL
29	1		*PANEL ASSY-QUARTER OUTER,LH (Supplementary)	Dented	1,349.00 FL	*1,349.00 FL
30	1		*MOULDING ASSY-FRT DR FRAME,LH (Supplementary)	Necessary	37.00 FL	*37.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,354.00	5,537.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,460.80	1,103.40
Total Parts (\$\$)	5,893.20	4,433.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON LH FRONT DOOR, LH REAR DOOR, CUT / WELD PANEL-SIDE SILL OUTRER LH, REPAIR LH REAR FENDER	New	2,400.00	1,800.00
2	TO TRANSFER LH FRONT DOOR GLASS, DOOR TRIM, MECHANISM AND OTHERS ATTACHMENT TO NEW DOOR PANEL	New	120.00	120.00
3	TO TRANSFER LH REAR DOOR GLASS, DOOR TRIM, MECHANISM AND OTHERS ATTACHMENT TO NEW DOOR PANEL	New	120.00	120.00
4	TO REMOVE AND INSTALL FLOOR CABIN, TRIM CABIN TO FACILITATE REPAIR WORK	New	120.00	120.00
5	PAINT WORK SPRAY LH FRONT DOOR, LH FRONT DOOR HANDLE, LH REAR DOOR, PANEL-SIDE SILL OUTRER, LH, LH REAR FENDER AND AFFECTED PORTION	New	1,750.00	1,480.00
6	SUPPLY BODY SEALANT	New	120.00	80.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	PERFORM RUST PREVENTION	New	120.00	40.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
10	REMOVE & REINSTALL LH SEATS TO FACILITATE REPAIR (Supplementary)	New	200.00	200.00
11	CUT & WELD TO REPLACE LH REAR FENDER (Supplementary)	New	800.00	800.00
			Gross Labour Cost (\$\$)	4,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >