

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC21004326/T1vcn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	05-05-2021 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJX 2714R	_	nspected	SHD 3310U	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1129687-001	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	05/04/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU093148	Colou	r	BLUE	
	Odometer	-	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST	LAKE	6 mm	
	L/H Front Tyre	205/60 R16	WEST	LAKE	6 mm	
	R/H Rear Tyre	205/60 R16	WEST	LAKE	6 mm	
	L/H Rear Tyre	205/60 R16	WEST	LAKE	6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	Date 01/04/2021 Inspection Date 05/04/2021				
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					