

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III20008937/GTF3E2-1

Date: 17/06/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMK7983E	Insured Vehicle No :	SH9102M
Date of Loss:	20/08/2020	Nature of Claim:	TP
		Claim No:	MCT20080305

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK7983E	Engine No:	G4LCKU162226
Make & Model:	HYUNDAI ACCENT, 1.4 (A)	Chassis No:	KMHCU41BT KU466335
Reg. Date:	25/04/2019 (Man. Year: 2019)	Odometer:	30071 km
Colour:	Silver		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,555.60	706.00	2,849.60	80.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	750.00	2,050.00	73.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,355.60	1,456.00	4,899.60	77.09
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	6,355.60	1,150.00	5,205.60	81.91
+ GST 7.00/7.00% (S\$)	444.89	80.50	364.39	81.91
Nett Amount (S\$)	6,800.49	1,230.50	5,569.99	81.91

INSPECTION

Date of Assignment:	06/04/2021		
Date Inspected:	25/08/2020	Inspected At:	53 Ubi Ave 1 #01-16, Paya Ubi Industrial Park
Estimated Period of Repair:	3.0 days		Repairer : Teamwork Garage Pte Ltd (HQ)

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2021)
Parts:	143	HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK7983E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	680.00 FL	*483.00 FL
2	2		*REAR BUMPER BRACKET	Serviceable	116.00 FL	*- FL
3	2		*REAR BUMPER RETAINER	Serviceable	45.00 FL	*- FL
4	1		*REAR BUMPER SPONGE	Serviceable	137.00 FL	*- FL
5	1		*REAR FENDER RH	Repair	1,406.00 FL	*- FL
6	1		*REAR FENDER INNER SHIELD	Serviceable	115.00 FL	*- FL
7	1		*REAR TAILLAMP RH	Serviceable	395.00 FL	*- FL
8	1		*REAR WINDSCREEN MOULDING	Serviceable	129.00 FL	*- FL
9	1		*REAR SHOCK ABSORBER RH	Serviceable	619.00 FL	*- FL
10	1		*REAR WHEEL HUB AND BEARING RH	Jammed	310.00 FL	*232.00 FL
11	1		*WHEEL TRIM COVER	Grazed	130.00 FL	*130.00 FL
12	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*20.00 FS
13	1		*SET REAR FENDER INNER SHIELD CLIP	Necessary	20.00 FS	*10.00 FS
14	1		*WINDSCREEN SEALANT	Serviceable	120.00 FS	*- FS
15	1		*JOINT SEALANT	Serviceable	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,372.00	875.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	816.40	169.00
Total Parts (\$\$)	3,555.60	706.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	New	70.00	0.00
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	New	150.00	0.00
3	REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	40.00
4	REMOVE AND REFIT REAR WINDSCREEN	New	120.00	0.00
5	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT	New	120.00	60.00
6	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS	New	200.00	50.00
7	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	200.00
8	SPRAY PAINTNG ON AFFECTED AREAS	New	900.00	400.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (S\$)			2,800.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >