



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 7983E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CRACKED	680.00	483.00
2	REAR BUMPER BRACKET	SERVICEABLE	116.00	-
2	REAR BUMPER RETAINER	SERVICEABLE	45.00	-
1	REAR BUMPER SPONGE	SERVICEABLE	137.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,406.00	-
1	REAR FENDER INNER SHIELD	SERVICEABLE	115.00	-
1	REAR TAILLAMP RH	SERVICEABLE	395.00	-
1	REAR WINDSCREEN MOULDING	SERVICEABLE	129.00	-
1	REAR SHOCK ABSORBER RH	SERVICEABLE	619.00	-
1	REAR WHEEL HUB AND BEARING RH	JAMMED	310.00	232.00
1	WHEEL TRIM COVER	GRAZED	130.00	130.00
	LESS 20% DISCOUNT		-816.40	-169.00
			3,265.60	676.00
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	20.00
1	SET REAR FENDER INNER SHIELD CLIP (SN)	NECESSARY	20.00	10.00
1	WINDSCREEN SEALANT (SN)	SERVICEABLE	120.00	-
1	JOINT SEALANT (SN)	SERVICEABLE	120.00	-
			290.00	30.00
<u>LABOUR</u>				
	CHECK REAR WIRING AND LIGHTNING SYSTEM.	NOT NECESSARY	70.00	-
	REMOVE, REFIT REAR LINING, TRIM AND GARNISH.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT REAR REVERSE SENSOR.		120.00	40.00
	REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE AND RENEW REAR UNDERCARRIAGE PARTS.		200.00	50.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		1,000.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS.		900.00	400.00

Report Ref No. CS3/III20008937/Gtf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
			2,800.00	750.00
	GRAND TOTAL		6,355.60	1,456.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,150.00

Report Ref No. CS3/III20008937/Gtf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.