

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |  |                 |                          |  |
|---|---|--|-----------------|--------------------------|--|
|   | INDIA INTERNATION   | ONAL INSURANCE PL  | Ref:            | CS3/III20008937/Gtf3e2-1 |  |
|   | 64 CECIL STREET<br>#05-02 IOB BUILD   | ING SINGAPORE 049711                                     | Date:           | 23/04/2021               |  |
|   |   |  | Code:           | III2                     |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM   |  |                 |                          |  |
|   | Insured Veh.  | SH 9102M   | Veh. Inspected  | SMK 7983E                |  |
|   | Policy No.  | MCOM0015   | Coverage (\$)   | 0.00                     |  |
|   | Claim No.   | MCT20080305  | Excess (\$)     | 0.00                     |  |
|   | Assign From   | CARINE KEK PHER SER                                      | Assign Date     | 06/04/2021               |  |
| 2.  | 2. Vehicle Particulars & Condition  |  |                 |                          |  |
|   | Make & Model  | HYUNDAI ACCENT 1.4                                       | c.c             | 1368                     |  |
|   | Engine No.  | HIDDEN   | Year of Reg.    | 2019                     |  |
|   | Chassis No.   | KMHCU41BTKU466335  | Colour          | SILVER                   |  |
|   | Odometer  | 30071 KM   | Steering        | IN ORDER                 |  |
|   | Brakes  | IN ORDER   | Modification    | NIL                      |  |
|   | General   | GOOD   |                 |                          |  |
| 3.  | 3. Conditions of Tyres  |  |                 |                          |  |
|   |   | Size   | Make            | Balance                  |  |
|   | R/H Front Tyre  | 175/70 R14   | KUMHO           | 6 mm                     |  |
|   | L/H Front Tyre  | 175/70 R14   | KUMHO           | 6 mm                     |  |
|   | R/H Rear Tyre   | 175/70 R14   | KUMHO           | 6 mm                     |  |
|   | L/H Rear Tyre   | 175/70 R14   | KUMHO           | 6 mm                     |  |
| 4.  | Description of Damages  |  |                 |                          |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  |  |                 |                          |  |
|   | DAMAGES SEE DETAILS.  |  |                 |                          |  |
| 5.  | General Information   |  |                 |                          |  |
|   | Accident Date   | 20/08/2020   | Inspection Date | 25/08/2020               |  |
|   | Survey held at  | ey held at 53 Ubi Ave 1 #01-16, Paya Ubi Industrial Park |                 |                          |  |
|   | Repairer  | rer TEAMWORK GARAGE PTE LTD                              |                 |                          |  |
| 5a.   | Remarks   |  |                 |                          |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |                          |  |
| 5b.   | Estimate Days of Repair   |  |                 |                          |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days  |  |                 |                          |  |
|   |   |  |                 |                          |  |