



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2204613

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 26/07/2022
Reference CC4/LPC21004335/Rea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMK 911J
Insured Veh. XD 5915Y
Claim No. 20/21/21/VC05/02438
Policy No. Z20VC05005974
Accident Date 30/03/2021
Inspection Date 06/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21004335/Rea3q2 Date: 26/07/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 5915Y	Veh. Inspected	SMK 911J	
Policy No.	Z20VC05005974	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/02438	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	06/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6 SEDAN 2.0 AT EX	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JM6GL1072K0311879	Colour	RED	
Odometer	46887 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S & O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/03/2021	Inspection Date	06/04/2021	
Survey held at	27A Tanjong Penjuru Singapore 609042			
Repairer	TRANS EUROKARS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			20 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 911J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,211.90	1,211.90
2	GROMMET SCREW	NECESSARY	5.80	5.80
1	RETAINER LHF BUMPER	NECESSARY	14.70	14.70
1	RETAINER RHF BUMPER	NECESSARY	17.10	17.10
1	COVER (L) ,BUMPER (INSIDE)	NOT NECESSARY	30.20	-
1	COVER (R) ,BUMPER (INSIDE)	NOT NECESSARY	30.20	-
8	RIVET	NECESSARY	32.00	32.00
1	PLATE (L),SEAL -F,BUMPER	NOT NECESSARY	78.90	-
1	PLATE (R),SEAL -F,BUMPER	NOT NECESSARY	78.90	-
4	RIVET	NECESSARY	18.00	18.00
1	FOGLAMP GARNISH LH	NOT NECESSARY	65.80	-
1	FOGLAMP GARNISH RH	NOT NECESSARY	65.80	-
1	FOGLAMP BASE GARNISH LH	NOT NECESSARY	20.50	-
1	LOWER GRILLE CAP LH	NOT NECESSARY	60.50	-
1	LOWER GRILLE CAP RH	NOT NECESSARY	60.50	-
1	FOGLAMP BASE GARNISH RH	NOT NECESSARY	20.50	-
1	STIFFA BUMPER GL3	NECESSARY	99.80	99.80
1	FRONT BUMPER SPONGE	CRACKED	60.60	60.60
2	CLIP FOR BUMPER SPONGE	NECESSARY	12.40	12.40
1	REINF,FRT BUMPER GL3	BENT	579.90	579.90
2	FRONT BUMPER SENSOR	SCRATCHED (1 PCS ONLY)	361.60	180.80
1	GRILLE TOP	SCRATCHED	453.80	453.80
6	RIVET FOR GRILLE TOP	NECESSARY	55.20	55.20
1	GRILLE TOP BRACKET RH	NOT NECESSARY	14.50	-
1	GRILLE TOP BRACKET LH	CRACKED	14.50	14.50
8	RIVET (NEC)	NECESSARY	32.00	32.00
1	SUPPORT TOP COVER	CRACKED	46.50	46.50
1	FRONT SUPPORT PANEL TOP BRACKET	CRACKED	95.00	95.00
4	FASTENER FOR SUPPORT BRACKET	NECESSARY	12.80	12.80
1	FRONT BUMPER BRACKET LOWER RH	NOT NECESSARY	37.10	-

Report Ref No. CC4/LPC21004335/Rea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER BRACKET LOWER LH	NOT NECESSARY	37.10	-
1	BRACKET (L),F BUMPER SIDE GL3	NECESSARY	37.10	37.10
1	BRACKET RHF BUMPER SIDE GL3	NECESSARY	37.10	37.10
2	PIN LOCATOR	NECESSARY	5.80	5.80
1	FRONT GRILLE BASE	CRACKED	133.70	133.70
1	FRONT GRILLE MESH	CRACKED	180.40	180.40
1	CLIP (NEC)	NECESSARY	9.10	9.10
1	FRONT GRILLE CHROME GARNISH LH	CRACKED	251.40	251.40
1	FRONT GRILLE CHROME GARNISH RH	NOT NECESSARY	251.40	-
1	FRONT GRILLE LOGO	NECESSARY	55.50	55.50
1	BRACKET ,RAD ,GRILLE LOGO	CRUMPLED	106.50	106.50
1	WIPER GARNISH RH	DEFORMED	15.50	15.50
1	WIPER GARNISH LH	NOT NECESSARY	15.50	-
1	BONNET	BENT	1,264.60	1,264.60
1	INSULATOR ,BONNET	NOT NECESSARY	189.00	-
1	HINGE (L),BONNET	BENT	118.10	118.10
1	HINGE (R),BONNET	BENT	114.40	114.40
2	TAPE ,PROTECTOR -STOPP	NECESSARY	10.80	10.80
1	WTHSTP PARTING SEAL	NOT NECESSARY	104.10	-
1	WTHSTP ,BONNET -FRT	CUT	32.90	32.90
1	LOCK ,BONNET	NOT NECESSARY	186.20	-
1	FRONT SUPPORT TOP PANEL	BENT	121.40	121.40
1	STAY ,LOCK	NOT NECESSARY	43.10	-
1	SUPPORT PANEL	CRACKED	418.10	418.10
1	GRILLE UNDER	NOT NECESSARY	764.40	-
1	SUPPORT PANEL SUPPORT	BENT	156.90	156.90
4	FASTENER	NECESSARY	12.80	12.80
1	FENDER RHF	BENT	383.70	383.70
1	FENDER LHF	BENT	383.70	383.70
1	GUARD RHF MUD	DEFORMED	114.30	114.30
1	GUARD LHF MUD	DEFORMED	114.30	114.30
1	STAY (L) ,FENDER	NOT NECESSARY	48.30	-
1	STAY (R) ,FENDER	NOT NECESSARY	48.30	-

Report Ref No. CC4/LPC21004335/Rea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
20	UNDERSHIELD CLIPS	NECESSARY	60.00	60.00
6	FASTENER CLIPS	NECESSARY	18.00	18.00
1	FRONT DOOR OUTER MOULDING RH	CUT	96.00	96.00
1	GARNISH RHR DOOR C-PILLAR	NECESSARY	54.60	54.60
1	GARNISH RHR DOOR B-PILLAR	NECESSARY	116.10	116.10
1	GARNISH (R),RHF DOOR (PIANO BLACK)	NECESSARY	99.20	99.20
1	STRIPE NO.1 (R) ,BODY SIDE	NECESSARY	11.00	11.00
1	STRIPE NO.3 (R) ,BODY SIDE	NECESSARY	12.90	12.90
1	STRIPE NO.2 (R) ,BODY SIDE	NECESSARY	11.90	11.90
1	STRIPE UPPER RHR DR	NECESSARY	15.50	15.50
1	FRONT DOOR RH	BENT	975.20	975.20
1	HINGE (R) DOOR -UPPER DJ/KE/KG	NOT NECESSARY	37.40	-
1	HINGE 'B' DR-LHF LWR DJ/BP/DM	NOT NECESSARY	37.80	-
1	WEATHERSTRIP RHF DR GL3	NECESSARY	90.60	90.60
1	FRONT DOOR GLASS RH	CRACKED	471.10	471.10
1	FRONT DOOR RUN CHANNEL RH	NOT NECESSARY	140.90	-
1	FRONT DOOR HANDLE	SCRATCHED	212.50	212.50
1	FRONT DOOR HANDLE CAP	NOT NECESSARY	24.70	-
1	FRONT DOOR HANDLE UNDERLAY	NOT NECESSARY	5.70	-
1	FRONT DOOR HANDLE BASE RH	NOT NECESSARY	77.00	-
1	SEAT (L),HANDLE -OUT GL/KG	NOT NECESSARY	5.70	-
1	FRONT DOOR LOCK RH	NOT NECESSARY	216.70	-
1	CARRIER (FRT,R) DOOR	NOT NECESSARY	116.30	-
1	MOTOR (R) WINDOW	NOT NECESSARY	166.70	-
4	PLUG HOLE (NEC)	NECESSARY	13.60	13.60
1	ARM/BASE RHF WINDOW	NOT NECESSARY	133.10	-
2	CHECK FRT DR	NOT NECESSARY	94.40	-
2	COVER ,HOLE (NEC)	NECESSARY	10.40	10.40
1	FRONT DOOR RH INNE TRIM	NOT NECESSARY	2,427.50	-
18	FASTENER CLIP FOR TRIM	NECESSARY	129.60	129.60
2	FASTENER CLIPS	NECESSARY	4.80	4.80
1	REAR DOOR RH	BENT	1,312.10	1,312.10
1	HINGE 'B' RHR DR SKYACTIV	NOT NECESSARY	44.80	-

Report Ref No. CC4/LPC21004335/Rea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MKD53-72-210A/HINGE 'B' LHR DR SKYACTIV	NOT NECESSARY	48.30	-
1	WEATHERSTRIP RHR DOOR	NOT NECESSARY	143.10	-
1	REAR DOOR RH OUTER HANDLE	SCRATCHED	78.90	78.90
1	REAR DOOR HANDLE CAP	TO REPAIR SEE LABOUR	22.30	-
1	REAR DOOR HANDLE UNDERLAY	NOT NECESSARY	5.70	-
1	REAR DOOR HANDLE BASE	NOT NECESSARY	59.60	-
2	CHECKER RH ,REAR DOOR	NOT NECESSARY	113.80	-
1	LOCK RHR DR	NOT NECESSARY	234.20	-
2	STICKER DR	NOT NECESSARY	54.40	-
1	MOTOR (R) WINDOW	NOT NECESSARY	166.70	-
1	PLUG ,HOLE (NEC)	NECESSARY	6.80	6.80
1	CARRIER RHR DOOR GL	NOT NECESSARY	96.20	-
1	COVER RHR ,HOLE -DOOR IN	NOT NECESSARY	35.70	-
1	REAR FENDER RH	BENT	1,312.50	831.25
1	SIDE MIRROR RH	BROKEN	475.90	475.90
1	SIDE MIRROR BASE GASKET	NECESSARY	13.30	13.30
1	SIDE MIRROR GLASS	BROKEN	282.50	282.50
1	SIDE MIRROR LIGHT RH	BROKEN	85.80	85.80
6	SCREW ,DOOR MIRROR	NECESSARY	108.00	108.00
1	SIDE MIRROR COVER HOUSING	MISSING	128.40	128.40
8	CAP ,ASSIST HANDLE	NOT NECESSARY	80.00	-
2	WHEEL DISC 17"X7 GL	SCRATCHED	2,393.60	2,393.60
2	VALVE AIR	NECESSARY	13.40	13.40
2	CAP CENTER RIM BM/BN/BP	NOT NECESSARY	43.20	-
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	392.40	-
2	RUBBER SPRING SEAT	NOT NECESSARY	46.80	-
2	STOPPER BUMPER GL	NOT NECESSARY	58.20	-
2	BEARING ,FRONT STRUT	NOT NECESSARY	111.60	-
2	SHOCK ABSORBER MOUNTING	NOT NECESSARY	193.00	-
1	LOWER ARM RH	NOT NECESSARY	503.90	-
1	KNUCKLE ARM RH	NOT NECESSARY	378.10	-
2	WHEEL HUB W/BEARING	NECESSARY	1,133.40	566.70

Report Ref No. CC4/LPC21004335/Rea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR GJ/GL (ADDITIONAL)	BENT	1,015.50	1,015.50
1	CONDENSER BM/BN (ADDITIONAL)	BENT	1,116.20	1,116.20
2	BOLT ,FLANGE (ADDITIONAL)	CRACKED	5.60	5.60
1	COVER ,UNDER FRT GL (ADDITIONAL)	CRACKED	75.30	75.30
1	BRACKET LHF GRILL GL (ADDITIONAL)	DEFORMED	15.50	15.50
1	MGSK4-51-031/HEADLAMP RH IPM3 GL (ADDITIONAL)	BROKEN	4,759.30	4,278.05
1	MGSK4-51-041/HEADLAMP LH IPM3 GL (ADDITIONAL)	BROKEN	4,759.30	4,278.05
1	PROTECTOR LHF HL GL3 (ADDITIONAL)	CRACKED	102.00	102.00
1	SENSOR ,ULTRASONIC S/ACTIV (ADDITIONAL)	CRACKED	200.50	200.50
1	COVER UNDER BM/BN/GL (ADDITIONAL)	CRACKED	300.90	300.90
1	SHIELD (R) ,SPLASH GL3 (ADDITIONAL)	CUT	16.40	16.40
1	MEMBER CROSS FRT GL/KF (ADDITIONAL)	BENT	1,731.70	1,250.45
1	BRACKET (L),HEAD LAMP GL3 (ADDITIONAL)	CRACKED	30.80	30.80
1	BRACKET LHF HL GL3 (ADDITIONAL)	CRACKED	15.50	15.50
1	PANEL (L) SHROUND -SIDE GL3 (ADDITIONAL)	BENT	134.60	134.60
1	LABEL ,CAUTION (ADDITIONAL)	NECESSARY	3.50	3.50
1	LABEL ,CAUTION (ADDITIONAL)	NECESSARY	3.50	3.50
1	SHIELD (R) ,SPLASH GL3 (ADDITIONAL)	CUT	52.30	52.30
1	GARNISH (R) ,SAIL -OUT GJ (ADDITIONAL)	CRACKED	116.30	116.30
1	COOLANT LONG LIVE 1LT (ADDITIONAL)	NECESSARY	13.70	13.70
1	COOLANT LONG LIVE 4 LTS (ADDITIONAL)	NECESSARY	54.80	54.80
	MOULD ,RR,WINDOW GL (ADDITIONAL)	NECESSARY	117.10	117.10
1	MOULD (R) ,FRT .SASH 'A' (ADDITIONAL)	NECESSARY	125.50	125.50
1	GUARD STONE CHIP GJ (ADDITIONAL)	NECESSARY	17.40	17.40
			40,299.20	29,060.00
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	280.00	20.00
			280.00	20.00
	<u>LABOUR</u>			
	TO REPAIR /PULLING THE FRONT CHASSIS FRAME MEMBER LH .(ADDITIONAL)		1,980.00	990.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PULLDOWN ENGINE TO GIVE WAY ON THE REPAIR OF THE FRONT CHASSIS FRAME MEMBER LH . (ADDITIONAL)		1,260.00	660.00
	TO SPRAY FRONT CHASSIS MEMBER LH (ADDITIONAL)		750.00	630.00
	TO PULLDOWN UNDERCARRIAGE TO GIVE WAY ON THE REPAIR OF THE FRONT CHASSIS FRAME MEMBER LH . (ADDITIONAL)		660.00	660.00
	TO MOUNT THE VEHICLE ONTO THE CELETTE BENCH & CORRECT CHASSIS CONFIGURATION TO FACTORY SPEC.(ADDITIONAL)		990.00	660.00
	TO REMOVE & REPLACE THE BONNET ,FRONT BUMPER ,FRONT FENDER LH & RH ,FRONT DOOR RH ,REAR DOOR RH ,REAR FENDER RH ,SIDE MIRROR RH ,FRONT SUPPORT PANEL ,BUMPER REINFORCEMENT & ALL ACCIDENT DAMAGE AREAS .TO REPAIR A-PILLAR RH & ALL AREAS AFFECTED BY THE ACCIDENT .INCLUSIVE OF THE REPAIR OF REAR DOOR HANDLE CAP .		8,250.00	6,600.00
	TO RESPRAY BONNET ,FRT BUMPER ,FRT FENDER LH ,FRT FENDER RH ,FRT DOOR RH ,REAR DOOR RH ,REAR FENDER RH ,SIDE MIRROR COVER RH ,A-PILLAR RH .		5,985.00	5,040.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		350.00	250.00
	TO CARRY OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO REMOVE & REPLACE RADIATOR & CONDENSER TO GIVE WAY ON THE REPLACEMENT OF FRONT SUPPORT PANEL.		660.00	330.00
	TO TOP UP AIRCON GAS.		280.00	180.00
	TO REMOVE & REPLACE FRONT UNDERCARRIAGE RH .		990.00	660.00
	TO REPLACE /SUPPLY 4PC OF TYRE 225/55 R17 .		1,800.00	900.00
	TO MOUNT 2PCS OF RIM & CONDUCT WHEEL BALANCING.		240.00	240.00
	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT.		560.00	560.00
	TO TRANSFER THE FRONT DOOR & REAR DOOR MECHANISM .		660.00	660.00
	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS .		560.00	560.00
	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS .		120.00	120.00
	TO REPLACE THE FRONT DOOR GLASS .		350.00	150.00
	TO SUPPLY SOLAR FILM ON THE FRONT DOOR GLASS .		140.00	140.00
	TO TRANSFER THE FRONT BUMPER SENSORS.		300.00	150.00

Report Ref No. CC4/LPC21004335/Rea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	180.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	250.00
	TO TOW THE VEHICLE FRONT THE ACCIDENT SITE TO THE WORKSHOP.		200.00	200.00
			27,935.00	20,920.00
GRAND TOTAL			68,514.20	50,000.00
RECOMMENDED COST OF REPAIRS				50,000.00

Report Ref No. CC4/LPC21004335/Rea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 911J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 911J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

