

TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

ATTN.:

FAX:

NAME:

ADDRESS:

TEL:

WIP:

31820

EXCESS:

DATE:

6-Apr-21

VEH NO:	SMK911J	DATE IN:	CONTACT PERSON:	EVA
CHASSIS NO:	JM6GL1072K0311879	MILEAGE:	TYPE OF CLAIM:	THIRD PARTY
MODEL:	MAZDA6	DATE REG:	POLICY NO.:	

NATURE OF WORKS

Parts Description

1	FRONT BUMPER <i>de/</i>	MGSJ8-50-031 BB	1	-	1,211.90
2	GROMMET, SCREW <i>re/</i>	MGHP9-50-025	2	-	5.80
3	RETAINER LHF BUMPER <i>re/</i>	MGHP9-50-0U1C	1	-	14.70
4	RETAINER RHF BUMPER <i>de/</i>	MGHP9-50-0T1B	1	-	17.10
5	COVER(L), BUMPER (INSIDE) <i>? Xan</i>	MGSJ7-50-104	1	-	30.20
6	COVER(R), BUMPER (INSIDE) <i>? Xan</i>	MGSJ7-50-103	1	-	30.20
7	RIVET <i>re/</i>	MS51S-51-833	8	-	32.00
8	PLATE(L), SEAL-F. BUMPER <i>? Xan</i>	MGSJ7-50-1V0	1	-	78.90
9	PLATE(R), SEAL-F. BUMPER <i>? Xan</i>	MGSJ7-50-1U0	1	-	78.90
10	RIVET <i>re/</i>	MBBM4-50-355	4	-	18.00
11	FOGLAMP GARNISH LH <i>? Xan</i>	MGBVG-50-131	1	-	65.80
12	FOGLAMP GARNISH RH <i>Xan</i>	MGBVG-50-121	1	-	65.80
13	FOGLAMP BASE GARNISH LH <i>? Xan</i>	MGSJ7-50-102	1	-	20.50
14	LOWER GRILLE CAP LH <i>X An</i>	MGSJ7-50-M42	1	-	60.50
15	LOWER GRILLE CAP RH <i>X An</i>	MGSJ7-50-M32	1	-	60.50
16	FOGLAMP BASE GARNISH RH <i>X An</i>	MGSJ7-50-101	1	-	20.50
17	STIFF'A', BUMPER GL3 <i>X re/</i>	MGRF2-50-050A	1	-	99.80
18	FRONT BUMPER SPONGE <i>cm/</i>	MG48F-50-111	1	-	60.60
19	CLIP FOR BUMPER SPONGE <i>re/</i>	MFD01-68-AC3	2	-	12.40
20	REINF., FRT BUMPER GL3 <i>bt/</i>	MGSJ7-50-070	1	-	579.90
21	FRONT BUMPER SENSOR <i>see/</i>	MKD47-67-UC1 PR	1	180.80	361.60
22	GRILLE TOP <i>see/</i>	MGSJ7-50-7E1 PR	1	-	453.80
23	RIVET FOR GRILLE TOP <i>re/</i>	MTK21-50-355	6	-	55.20
24	GRILLE TOP BRACKET RH <i>X An</i>	MGSJ7-50-153	1	-	14.50
25	GRILLE TOP BRACKET LH <i>cm/</i>	MGSJ7-50-163	1	-	14.50
26	RIVET (NEC) <i>re/</i>	MS51S-51-833	8	-	32.00
27	SUPPORT TOP COVER <i>cm/</i>	MGHR1-50-1A1	1	-	46.50
28	FRONT SUPPORT PANEL TOP BRACKET <i>bt/ ? cm/</i>	MGSJ7-50-717A	1	-	95.00
29	FASTENER FOR SUPPORT BRACKET <i>re/</i>	MGD7A-50-EA1	4	-	12.80
30	FRONT BUMPER BRACKET LOWER RH <i>X An</i>	MGSJ7-50-151	1	-	37.10

	FRONT BUMPER BRACKET LOWER LH ? <i>xnn</i>	MGSH7-50-161	1				37.10
	BRACKET(L), F. BUMPER SIDE GL3 <i>ne</i>	MGSH7-50-162	1				37.10
scri3	BRACKET RHF BUMPER SIDE GL3 <i>nee</i>	MGSH7-50-152	1				37.10
34	PIN, LOCATOR <i>ne</i>	MKD45-50-1K5A	2				5.80
35	FRONT GRILLE BASE <i>cm</i>	MGSH7-50-712B	1				133.70
36	FRONT GRILLE MESH <i>cm</i>	MGSH7-50-719	1				180.40
37	CLIP (NEC) <i>ne</i>	MGSH7-50-EB1	1				9.10
38	FRONT GRILLE CHROME GARNISH LH <i>cm</i>	MGSH7-50-7K0D	1				251.40
39	FRONT GRILLE CHROME GARNISH RH ? <i>xnn</i>	MGSH7-50-7J0D	1				251.40
40	FRONT GRILLE LOGO <i>nee</i>	MG46L-51-730	1				55.50
41	BRACKET, RAD. GRILLE LOGO <i>cm</i>	MGBFN-50-716	1				106.50
42	WIPER GARNISH RH <i>de</i>	MGBEF-51-PB1	1				15.50
43	WIPER GARNISH LH <i>xnn</i>	MGBEF-51-PC1	1				15.50
44	BONNET <i>bt</i>	MGBY0-52-31XB	1				1,264.60
45	INSULATOR, BONNET <i>xnn</i>	MGBFN-56-681A	1				189.00
46	HINGE(L), BONNET <i>bt</i>	MGBFT-52-420E	1				118.10
47	HINGE(R), BONNET <i>bt</i>	MGBFT-52-410E	1				114.40
48	TAPE, PROTECTOR-STOPP <i>nee</i>	MC001-56-864A	2				10.80
49	WTHSTP, PARTING SEAL <i>bt</i> <i>nn</i>	MGHP9-56-770	1				104.10
50	WTHSTP, BONNET-FRT <i>cut</i>	MGHP9-56-750	1				32.90
51	LOCK, BONNET ? <i>xnn</i>	MGBGA-56-620A	1				186.20
52	FRONT SUPPORT TOP PANEL ? <i>bt</i>	MGSH7-53-150	1				121.40
53	STAY, LOCK ? <i>xnn</i>	MGHP9-52-15YA	1				43.10
54	SUPPORT PANEL <i>cm</i> / <i>photo</i>	MGHP9-53-110B	1				418.10
55	GRILLE UNDER <i>xnn</i>	MGSH7-50-R10	1				764.40
56	SUPPORT PANEL SUPPORT ? <i>bt</i>	MGSH7-50-1C0B	1				156.90
57	FASTENER <i>ne</i>	MGD7A-50-EA1	4				12.80
58	FENDER RHF <i>bt</i>	MGHP9-52-111A	1				383.70
59	FENDER LHF <i>bt</i>	MGHP9-52-211A	1				383.70
60	GUARD RHF MUD <i>de</i>	MGRF2-56-130	1				114.30
61	GUARD LHF MUD <i>de</i>	MGRF2-56-140	1				114.30
62	STAY(L), FENDER ? <i>xnn</i>	MGHP9-52-240D	1				48.30
63	STAY(R), FENDER ? <i>xnn</i>	MGHZ9-52-1R0A	1				48.30
64	UNDERSHIELD CLIPS <i>nee</i>	MB45A-56-146A	20				60.00
65	FASTENER CLIPS <i>ne</i>	MJ21-68-885B02	6				18.00
66	FRONT DOOR OUTER MOULDING RH <i>at</i>	MGHP9-50-640F	1				96.00
67	GARNISH RHR DOOR C-PILLAR <i>ne</i>	MJR9-50-M50A	1				54.60
68	GARNISH RHR DOOR B-PILLAR <i>ne</i>	MGBFT-50-M30	1				116.10
69	GARNISH(R), RHF DOOR (PIANO BLACK) <i>nee</i>	MGBFT-50-M10	1				99.20
70	STRIPE NO.1(R), BODY SIDE <i>ne</i>	MGR6-50-8V1A00	1				11.00
71	STRIPE NO.3(R), BODY SIDE <i>ne</i>	MGR6-50-8V3A00	1				12.90
72	STRIPE NO.2(R), BODY SIDE <i>nee</i>	MGR6-50-8V2A00	1				11.90
73	STRIPE UPPER RHR DR <i>ne</i>	MGR6-50-8V4A00	1				15.50
74	FRONT DOOR RH <i>bt</i>	MGHY0-58-02XJ	1				975.20
75	HINGE(R), DOOR-UPPER DJ/KE/KG ? <i>xnn</i>	MKD53-58-210A	1				37.40
76	HINGE'B', DR-LHF LWR DJ/BP/DM ? <i>bt</i> <i>nn</i>	MD461-59-210B	1				37.80
77	WEATHERSTRIP RHF DR GL3 <i>ne</i>	MGBFN-58-760	1				90.60

	FRONT DOOR GLASS RH <i>ca /</i>	MGRT6-58-510B	1				471.10	✓
	FRONT DOOR RUN CHANNEL RH <i>? xnn</i>	MGRT6-58-605A	1				140.90	
80	FRONT DOOR HANDLE <i>scr /</i>	MTK49-58-41XCPR	1				212.50	✓
81	FRONT DOOR HANDLE CAP <i>xnn</i>	MD09L-58-415BPR	1				24.70	
82	FRONT DOOR HANDLE UNDERLAY <i>xnn</i>	MKD53-58-414	1				5.70	
83	FRONT DOOR HANDLE BASE RH <i>? xnn</i>	MGHP9-58-42XD	1				77.00	
84	SEAT(L),HANDLE-OUT GL/KG <i>? xnn</i>	MKD53-59-414	1				5.70	
85	FRONT DOOR LOCK RH <i>? xnn</i>	MGW0H-58-310A	1				216.70	
86	CARRIER(FRT,R),DOOR <i>? xnn</i>	MGBJD-58-97X	1				116.30	
87	MOTOR(R),WINDOW <i>? xnn</i>	MD651-58-58XB	1				166.70	
88	PLUG,HOLE (NEC) <i>rec /</i>	MF151-58-866	4				13.60	✓
89	ARM/BASE RHF WINDOW <i>? xnn</i>	MGHP9-58-590A	1				133.10	
90	CHECKER,FRT DR <i>? xnn</i>	MGBFN-58-270	2				94.40	
91	COVER,HOLE (NEC) <i>rec /</i>	MGHP9-58-972	2				10.40	✓
92	FRONT DOOR RH INNER TRIM <i>? xnn</i>	MGCCD-68-420E02	1				2,427.50	
93	FASTENER CLIP FOR TRIM <i>rec /</i>	MGJ6A-68-AB1	18				129.60	✓
94	FASTENER CLIPS <i>rec /</i>	MGE4T-68-865A	2				4.80	✓
95	REAR DOOR RH <i>bt /</i>	MGHY1-72-02XB	1				1,312.10	✓
96	HINGE'B'RHR DR SKYACTIV <i>? xnn</i>	MKD53-72-240A	1				44.80	
97	MKD53-72-210A/HINGE'B'LHR DR SKYACTIV <i>? xnn</i>	MKD53-72-210	1				48.30	
98	WEATHERSTRIP RHR DOOR <i>xnn</i>	MGBFN-72-760	1				143.10	
99	REAR DOOR RH OUTER HAND;E <i>scr /</i>	MTK48-58-41XBPR	1				78.90	✓
100	REAR DOOR HANDLE CAP <i>repair</i>	MD09W-58-415BPR	1				22.30	R
101	REAR DOOR HANDLE UNDERLAY <i>? xnn</i>	MKD53-58-414	1				5.70	
102	REAR DOOR HANDLE BASE <i>? xnn</i>	MGHP9-72-42XB	1				59.60	
103	CHECKER RH,REAR DOOR <i>? xnn</i>	MGBFN-72-270	2				113.80	
104	LOCK RHR DR <i>? xnn</i>	MGJT1-72-310A	1				234.20	
105	STRIKER DR <i>xnn</i>	MGS1D-58-361A	2				54.40	
106	MOTOR(R),WINDOW <i>? xnn</i>	MD651-58-58XB	1				166.70	
107	PLUG,HOLE (NEC) <i>rec /</i>	MF151-58-866	2				6.80	✓
108	CARRIER RHR DOOR GL <i>? xnn</i>	MGHP9-72-97XB	1				96.20	
109	COVER RHR,HOLE-DOOR IN <i>? xnn</i>	MG46G-72-973	1				35.70	
110	REAR FENDER RH <i>bt /</i>	MGSY7-70-41X	1			831.25	1,312.50	✓
111	SIDE MIRROR RH <i>br /</i>	MGS89-69-121A	1				475.90	✓
112	SIDE MIRROR BASE GASKET <i>rec /</i>	MGHP9-69-115	1				13.30	✓
113	SIE MIRROR GLASS <i>br /</i>	MB63C-69-1G1	1				282.50	✓
114	SIDE MIRROR LIGHT RH <i>br /</i>	MB63B-69-122A	1				85.80	✓
115	SCREW,DOOR MIRROR <i>rec /</i>	ML208-69-126	6				108.00	✓
116	SIDE MIRROR COVER HOUSING <i>rec /</i>	MB63B-69-1N1 PR	1				128.40	✓
117	CAP,ASSIST HANDLE <i>? scr xnn</i>	MGAL1-69-472A75	8				80.00	
118	WHEEL,DISC 17"X7 GL <i>scr /</i>	M9965-16-7570	2				2,393.60	✓
119	VALVE,AIR <i>rec /</i>	M9963-60-4140	2				13.40	
120	CAP,CENTER RIM BM/BN/BP <i>xnn</i>	MKD51-37-190	2				43.20	
121	FRONT SHOCK ABSORBER RH <i>? xnn</i>	MGBJD-34-700A	1				392.40	
122	RUBBER,SPRING SEAT <i>? xnn</i>	MKA0G-34-0A3	2				46.80	
123	STOPPER,BUMPER GL <i>? xnn</i>	MGBFN-34-111	2				58.20	
124	BEARING,FRONT STRUT <i>? xnn</i>	MB45A-34-38XA	2				111.60	

	SHOCK ABSORBER MOUNTING ? <i>kan</i>	MKD35-34-380C	2			-	193.00
6	LOWER ARM RH ? <i>kan</i>	MG46C-34-300J	1			-	503.90
127	KNUCKLE ARM RH ? <i>kan</i>	MGBFN-33-021	1			-	378.10
128	WHEEL HUB W/ BEARING ? <i>neu</i>	MKD35-33-04XF	2			56676	1,133.40
129			0			-	-
130			0			-	-
TOTAL PARTS							25,516.00
TOTAL PARTS COST							25,516.00

1	TO REMOVE & REPLACE THE, BONNET, FRONT BUMPER, FRONT FENDER LH & RH, FRONT DOOR RH, REAR DOOR RH, REAR FENDER RH, SIDE MIRROR RH, FRONT SUPPORT PANEL, BUMPER REINFORCEMENT & ALL ACCIDENT DAMAGE AREAS. TO REPAIR A-PILLAR RH & ALL AREAS AFFECTED BY THE ACCIDENT	<i>6600</i>	8,250.00
2	TO RESPRAY BONNET, FRT BUMPER, FRT FENDER LH, FRT FENDER RH, FRT DOOR RH, REAR DOOR RH, REAR FENDER RH, SIDE MIRROR COVER RH, A- PILLAR RH	<i>5040</i>	5,985.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	<i>280</i>	350.00
4	TO CARRY OUT BODY CAVITY PRESERVATION	<i>150</i>	250.00
5	TO REMOVE & REPLACE RADIATOR & CONDENSER TO GIVE WAY ON THE REPLACEMENT OF FRONT SUPPORT PANEL	<i>330</i>	660.00
6	TO TOP UP AIRCON GAS,	NETT <i>180</i>	280.00
7	TO REMOVE & REPLACE FRONT UNDERCARRIAGE RH	<i>660?</i>	990.00
8	TO REPLACE/ SUPPLY 4PC OF TYRE 225/55 R17 <i>(1pc)</i>	<i>900</i> NETT <i>450</i>	1,800.00
9	TO MOUNT 2PCS OF RIMS & CONDUCT WHEEL BALANCING	NETT	240.00
10	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT	NETT	560.00
11	TO TRANSFER THE FRONT DOOR & REAR DOOR MECHANISM	NETT	660.00
12	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS	NETT	560.00
13	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS	NETT	120.00
14	TO REPLACE THE FRONT DOOR GLASS	<i>150</i>	350.00
15	TO SUPPLY SOLAR FILM ON THE FRONT DOOR GLASS <i>(inmate)</i>	NETT	140.00

	TO TRANSFER THE FRONT BUMPER SENSORS	150/	300.00
17	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	NETT 180/	250.00
18	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	NETT 250/	350.00
19	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP (invoice)	- / ?	200.00
20	SUNDRIES	- 20/	280.00

TOTAL LABOUR	14,585.00
TOTAL PARTS	25,516.00
TOTAL	40,101.00
LESS EXCESS	-
TOTAL AFTER EXCESS	40,101.00
GST 7%	2,807.07
GRAND TOTAL	42,908.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

SUPPLEMENTARY PARTS

1	0	Date:	0	0					-
2	0		0	0					-
TOTAL PARTS									-
TOTAL PARTS COST									-
1		#N/A							-
2		#N/A							-

Rasul

Hp 90010068

20 # days

06/04/21 P1545

Resurvey after repair

SUPPLEMENT LABOUR	-	-
SUPPLEMENT PARTS	-	-
TOTAL SUPPLEMENT	-	-
	-	-
	-	-
GST 7%	-	-
GRAND TOTAL	-	-

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS

TRANS EUROKARS PTE LTD

TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

LONPAC INSURANCE BHD		NAME :		WIP :	
300 BEACH ROAD		ADDRESS :		EXCESS :	
#17-04/07 THE CONCOURSE				DATE:	
SINGAPORE 199555		TEL :		12-Apr-21	
ATTN. :					
FAX :					
VEH NO :	SMK911J	DATE IN :		CONTACT PERSON :	EVA
CHASSIS NO :	JM6GL1072K0311879	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 6	DATE REG:	26-Mar-19	POLICY NO. :	

NATURE OF WORKS

Parts Description

1	RADIATOR GJ/GL <i>bt</i>	MPE11-15-200B	1		-	1,015.50
2	CONDENSER BM/BN <i>bt</i>	MGHR1-61-480B	1		-	1,116.20
3	BOLT, FLANGE <i>an</i>	M9946-40-625	2		-	5.60
4	COVER, UNDER FRT GL <i>cm</i>	MGSH7-56-11Y	1		-	75.30
5	BRACKET LHF GRILL GL <i>de</i>	MGRG1-50-164	1		-	15.50
6	MGSK4-51-031/HEADLAMP RH IPM3 GL <i>bu</i>	MGSK4-51-031A	1		4,278.05	4,759.30
7	MGSK4-51-041/HEADLAMP LH IPM3 GL <i>bu</i>	MGSK4-51-041A	1		4,278.05	4,759.30
8	PROTECTOR LHF HL GL3 <i>cm</i>	MGRF5-51-075A	1		-	102.00
9	SENSOR, ULTRASONIC S/ACTIV <i>cm</i>	MGMC8-67-UC1	1		-	200.50
10	COVER, UNDER BM/BN/GL <i>cm</i>	MB61K-56-110A	1		-	300.90
11	SHIELD(R), SPLASH GL3 <i>cut</i>	MGRF2-56-114	1		-	16.40
12	MEMBER, CROSS FRT GL/KF <i>bt</i>	MKB7W-34-80XD	1		1,250.45	1,731.70
13	BRACKET(L), HEAD LAMP GL3 <i>cm</i>	MGSH7-50-ACXA	1		-	30.80
14	BRACKET LHF HL GL3 <i>cm</i>	MGSH7-50-ACYA	1		-	15.50
15	PANEL(L), SHROUD-SIDE GL3 <i>bt</i>	MG48F-54-140	1		-	134.60
16	LABEL, CAUTION <i>an</i>	MPE01-15-031	1		-	3.50
17	LABEL, CAUTION <i>an</i>	MKF49-61-439	1		-	3.50
18	SHIELD(R), SPLASH GL3 <i>cut</i>	MGSH7-50-340	1		-	52.30
19	GARNISH(R), SAIL-OUT GJ <i>cm</i>	MGJR9-69-15YB	1		-	116.30
20	COOLANT LONG LIVE 1LT <i>an</i>	M11-NAC9-15-001MM	1		-	13.70
21	COOLANT LONG LIVE 4 LTS <i>an</i>	M11-NAC9-15-004MM	1		-	54.80

TOTAL PARTS

- 14,523.20

TOTAL PARTS COST

- 14,523.20

1	TO REPAIR/ PULLING THE FRONT CHASSIS FRAME MEMBER LH	980	1,980.00
---	--	-----	----------

2		TO PULldOWN ENGINE TO GIVE WAY ON THE REPAIR OF THE FRONT CHASSIS FRAME MEMBER LH	NETT	660 1,260.00
3		TO SPRAY FRONT CHASSIS MEMBER LH		630 750.00
3		TO PULldOWN UNDERCARRIAGE TO GIVE WAY ON THE REPAIR OF THE FRONT CHASSIS FRAME MEMBER LH	NETT	660.00
3		TO MOUNT THE VEHICLE ONTO THE CELETTE BENCH & CORRECT CHASSIS CONFIGURATION TO FACTORY SPEC	plus?	660 990.00
3				

TOTAL LABOUR	5,640.00
TOTAL PARTS	14,523.20
TOTAL	20,163.20
LESS EXCESS	-
TOTAL AFTER EXCESS	20,163.20
GST 7%	1,411.42
GRAND TOTAL	21,574.62

SUPPLEMENTARY PARTS

1	MOULD, RR. WINDOW GL	✓ nec	0	1			117.10
2	MOULD(R), FRT.SASH 'A'	✓ nec	0	1			125.50
3	GUARD STONE RHR GJ	✓ nec		1			17.40
	TOTAL PARTS						-
							-
	TOTAL PARTS COST						-

1	#N/A						-
2	#N/A						-

SUPPLEMENT LABOUR	-	-
SUPPLEMENT PARTS	-	-
TOTAL SUPPLEMENT	-	-
	-	-
	-	-
GST 7%	-	-
GRAND TOTAL	-	-

TRANS EUROKARS PTE LTD

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS