

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004337/KPS3Q2
Date: 23/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900166708
Claimant Vehicle No :	GBK5716D	Insured Vehicle No :	SMP4092U
Date of Loss:	01/04/2021	Nature of Claim:	TP
		Claim No:	4975518286SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK5716D	Engine No:	D4CBL019764
Make & Model:	KIA K2500, 2.5 D 6M/T (M)	Chassis No:	KNCSJX76LL7454868
Reg. Date:	15/09/2020 (Man. Year: 2020)	Odometer:	12827 km
Colour:	Blue		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Kumho 9 mm	Rear Left Side:	Kumho 9/9 mm
Front Right Side:	Kumho 9 mm	Rear Right Side:	Kumho 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,743.10	1,603.60	139.50	8.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	895.00	780.00	115.00	12.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,638.10	2,383.60	254.50	9.65
Approved Total (Overridden) (S\$)		1,900.00		

Adjuster Report

	(S\$)	2,638.10	1,900.00	738.10	27.98
	+ GST 7.00/7.00% (S\$)	184.67	133.00	51.67	27.98
	Nett Amount (S\$)	2,822.77	2,033.00	789.77	27.98
	+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
	Nett Liability (S\$)		2,433.00		

INSPECTION

Date of Assignment: 06/04/2021

Date Inspected: 03/05/2021

Inspected At:

S & H Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT BUMPER RETAINER	Serviceable	45.00 FL	*- FL
2	1		*FRONT BUMPER	Dented / Cut	385.00 FL	*385.00 FL
3	1		*LH HEAD LAMP	Cut	365.00 FL	*365.00 FL
4	1		*LH FRONT CORNER PANEL	Bent	147.00 FL	*147.00 FL
5	1		*LH FRONT DOOR	Bent	764.00 FL	*764.00 FL
6	1		*LH FRONT DOOR SIGNAL LAMP	Broken	45.00 FL	*45.00 FL
7	1		*LH FRONT DOOR HINGE TOP	Repair	55.00 FL	*- FL
8	1		*LH FRONT DOOR HINGE BOTTOM	Repair	55.00 FL	*- FL
9	1		*LH FRONT DOOR K2500 STICKER	Necessary	48.00 FL	*48.00 FL
10	1		*LH FRONT DOOR COMPANY STICKER	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,934.00	1,779.00
- List Item Discount on L Items 10.00/10.00% (\$)	190.90	175.40
Total Parts (\$)	1,743.10	1,603.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY TO FOCUS HEADLAMP	New	25.00	20.00
2	TO REMOVE DAMAGED PARTS ,TO JACK OUT FRONT SUPPORT PANEL,FRONT BODY AND CUT OUT DAMAGED PARTS ,TO REWELD AND REPAIR LH FRONT CORNER PANEL HEAD LAMP INNER PANEL,FRONT SUPPORT PANEL ,FRONT CHASSIS MEMBER AND ADJUST BODY PANEL ALIGNMENT	New	420.00	400.00
3	TO SPRAY PAINT LH FRONT DOOR ,LH FRONT CORNER PANEL AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	450.00	360.00
			Gross Labour Cost (S\$)	780.00
			895.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >