

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21004346/UGA3Q2**Date:** 19/08/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	SLH4072G	Insured Vehicle No :	SHD2624X
Date of Loss:	05/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001499

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH4072G	Engine No:	1NZY455765
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305284716
Reg. Date:	30/01/2012 (Man. Year: 2011)	Odometer:	153696 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,107.20	4,029.05	9,078.15	69.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	2,610.00	1,660.00	38.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,377.20	6,639.05	10,738.15	61.79
Approved Total (Overridden) (\$\$)		5,300.00		
Nett Amount (\$\$)	17,377.20	5,300.00	12,077.20	69.50
+ Car Rental (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		60.00		
Nett Liability (\$\$)		5,767.45		

INSPECTION

Date of Assignment:	06/04/2021		
Date Inspected:	06/04/2021	Inspected At:	CHOO MOTOR SPRAY PAINTER 1 Kaki Bukit Ave 6, #01-39 Autobay Singapore 417883
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2021)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH4072G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	766.50 F	*- FL
2	1		*BOOTLID REAR LOGO	Necessary	68.50 F	*68.50 FL
3	1		*BOOTLID VIOS EMBLEM	Necessary	45.80 F	*45.80 FL
4	1		*BOOTLID E EMBLEM	Necessary	40.50 F	*40.50 FL
5	1		*BOOTLID OUTER HANDLE	Not Necessary	198.10 F	*- FL
6	1		*BOOTLID INNER LOCK	Not Necessary	199.40 F	*- FL
7	1		*BOOTLID LOCK STRIKER	Not Necessary	89.90 F	*- FL
8	1		*BOOTLID WEATHERSTRIP	Not Necessary	266.50 F	*- FL
9	1		*REAR BUMPER	Distorted	655.10 F	*468.20 FL
10	1		*REAR BUMPER SIDE RETAINERS	N/S Cracked	153.00 F	*45.50 FL
11	1		*REAR BUMPER BRACKETS	N/S Bent	198.20 F	*85.10 FL
12	1		*REAR BUMPER REFLECTORS	N/S Cracked	390.00 F	*161.10 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*REAR EXHAUST	Not Necessary	588.10 F	*- FL
15	2		*REAR EXHAUST MOUNTINGS	Not Necessary	130.00 F	*- FL
16	1		*REAR END PANEL	Badly Dented	655.20 F	*566.10 FL
17	1		*REAR END PANEL GARNISH	Twisted	315.10 F	*241.30 FL
18	1		*TAILLAMPS	N/S Cracked	1,040.20 F	*325.10 FL
19	1		*TAILLAMPS HOUSING PANELS	N/S Dented	399.00 F	*199.50 FL
20	1		*REAR FLOOR PANEL	Repair	911.20 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	422.50 F	*- FL
22	1		*REAR FLOOR PANEL SIDE TOOLS SPONGES	N/S Torn	778.20 F	*285.30 FL
23	1		*REAR FENDERS	N/S Buckled	1,690.20 F	*845.10 FL
24	1		*REAR FENDER INNER SPLASH SHIELDS	N/S Distorted	210.00 F	*82.50 FL
25	1		*REAR FENDER INNER TRIM N/S	Distorted	288.90 F	*242.10 FL
26	1		*SET REAR FENDER INNER TRIM CLIPS N/S	Not Necessary	50.00 F	*- FL
27	1		*REAR AIR VENT N/S	Distorted	108.60 F	*105.20 FL
28	1		*REAR WINDSCREEN MOULDING	Necessary	88.50 F	*88.50 FL
29	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
30	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
31	1		*SET REAR FLOOR PANEL SOUND PROOF INSULATOR	Necessary	800.00 FS	*350.00 FS
32	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
33	1		*SET REAR BUMPER LOWER SKIRTING	Cracked	1,080.00 FS	*600.00 FS
34	1		*SET REAR FENDER OUTER STRIP N/S	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,107.20	5,015.40
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	986.35
Total Parts (\$\$)	13,107.20	4,029.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	20.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	0.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO SPRAY RUST PROOFING	New	120.00	60.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	180.00	80.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	1,200.00
9	TO PUTTY & SPRAY PAINTING	New	1,680.00	1,100.00
Gross Labour Cost (S\$)			4,270.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >