

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21004347/R1tce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA Date: 15/04/2021 **TOWERSINGAPORE 068811** ATTN: CHAN KIAN CHUAN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHB 4245D YN 3284H Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M036YL Excess (\$) 0.00 **CHAN KIAN CHUAN Assign Date** 06/04/2021 Assign From **Vehicle Particulars & Condition** 2. HINO GH8JRKA 7684 Make & Model c.c HIDDEN 2012 Engine No. Year of Reg. GH8JRK12575 WHITE Chassis No. Colour 297795 KM Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 10.00 R20 LONG MARCH 7 mm 10.00 R20 L/H Front Tyre LONG MARCH 7 mm 10.00 R20 (D) LONG MARCH R/H Rear Tyre 7/7 mm 7/7 mm 10.00 R20 (D) LONG MARCH L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 31/03/2021 07/04/2021 (03:25 PM) **Accident Date** Inspect Date / Time 7 PENJURU CLOSE LEVEL 1 Survey held at Repairer VFIX AUTO SERVICE PTE LTD 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000

Report Ref No. CS3/ASM21004347/R1tce2

Estimate Days of Repair

Inspected By

Automotive Assessor

5b.

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

5 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser