

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004350/EPA3Q2
Date: 18/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700090614
Claimant Vehicle No :	SMQ3525P	Insured Vehicle No :	SLV1391G
Date of Loss:	13/03/2021	Nature of Claim:	TP
		Claim No:	3426835712SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ3525P	Engine No:	4J11BH5944
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0601993
Reg. Date:	12/11/2019 (Man. Year: 2019)	Odometer:	14885 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 4 mm	Rear Left Side:	Toyo 4 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,304.19	2,744.40	559.79	16.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,870.00	1,090.00	1,780.00	62.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,174.19	3,834.40	2,339.79	37.90
+ GST 7.00/7.00% (S\$)	432.19	268.41	163.78	37.90

Nett Amount (S\$)	6,606.38	4,102.81	2,503.57	37.90
+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)		385.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,490.01		

INSPECTION

Date of Assignment: 06/04/2021

Date Inspected: 06/04/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)

209 Pandan Gardens

Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*BODY KIT ,OUTLANDER	Broken	1,554.00 FS	*1,554.00 FS
3	1		*FACE ,RR BUMPER	Cut	624.47 FS	*624.47 FS
4	1		*BRKT ,R/BMPR FACE SIDE ,LH	Not Necessary	9.24 FS	*- FS
5	8		*CLIP ,ENG ROOM COVER	Not Necessary	12.32 FS	*- FS
6	1		*REINFORCEMENT ,RR BUMPER ,LH	Not Necessary	60.83 FS	*- FS
7	1		*EXTENSION ,RR BUMPER	Not Necessary	277.20 FS	*- FS
8	1		*LAMP ASSY ,COMB ,RR LH	Cut	464.31 FS	*464.31 FS
9	1		*REFLECTOR ,TAIL LAMP LH	Not Necessary	77.00 FS	*- FS
10	1		*MOULDING ,RR BUMPER ,LH	Necessary	81.62 FS	*81.62 FS
11	1		*MOULDING ,RR WHEEL ARCH ,LH	Not Necessary	123.20 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	
					3,304.19	2,744.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER & BODY KIT REPAIR LHR FENDER	New	1,350.00	530.00
2	RESPRAY RR BUMPER ,RR BUMPER BODY KIT & LHR FENDER	New	1,310.00	350.00
3	CHECK WIRING ELECTRICAL	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
Gross Labour Cost (S\$)			2,870.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >