

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004359/T1RA3Q2**Date:** 13/01/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHC7938M**Insured Vehicle No :** SKR8367P

Date of Loss: 05/04/2021

Nature of Claim: TP

Claim No: 0099475655SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC7938M**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Engine No: 2ZR2B89866

Reg. Date: 09/01/2019 (Man. Year: 2018)

Chassis No: JTDKB3FU003078307

Colour: Yellow

Odometer: 250114 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,128.22	3,941.87	1,186.35	23.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	1,055.00	425.00	28.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,608.22	4,996.87	1,611.35	24.38
+ GST 7.00/7.00% (S\$)	462.58	349.78	112.80	24.38
Nett Amount (S\$)	7,070.80	5,346.65	1,724.15	24.38
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$126.47/day) (S\$)		252.94		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,701.59		

INSPECTION

Date of Assignment: 06/04/2021

Date Inspected: 06/04/2021 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	499.90 FL	*499.90 FL
2	1		*FRT BUMPER HOLE COVER RH	Cut	28.40 FL	*28.40 FL
3	1		*FRT BUMPER SIDE SUPPORT R	Not Necessary	77.00 FL	*- FL
4	1		*HEADLAMP RH	Cut	3,455.00 FL	*3,455.00 FL
5	1		*FOGLAMP RH	Cut	920.00 FL	*920.00 FL
6	1		*FRT FENDER RH	Repair	945.30 FL	*- FL
7	1		*FRT FENDER SHIELD RH	Not Necessary	198.40 FL	*- FL
8	1		*FRT FENDER (HYBRID) RH	Necessary	52.30 FL	*52.30 FL
9	1		*RADIATOR UPR GRILLE	Not Necessary	361.10 FL	*- FL
10	1		*RADIATOR LWR GRILLE	Cut	166.90 FL	*166.90 FL
11	1		*FRT FENDER ADV.STICKER RH	Necessary	100.00 FS	*100.00 FS
					Sub Total (\$\$)	6,804.30 5,222.50
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,676.08 1,280.63
					Total Parts (\$\$)	5,128.22 3,941.87

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	525.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	CHECK ALL LIGHTING	New	40.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	40.00	0.00
Gross Labour Cost (\$\$)			1,480.00	1,055.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >