

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 1542A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	BROKEN	1,245.70	895.00
1	FRONT BUMPER RH FOG LAMP (CONSISTENT)	NOT DAMAGED	352.10	-
1	FRONT BUMPER RH SIDE RETAINER (CONSISTENT)	NECESSARY	90.70	66.20
1	FRONT BUMPER LH SIDE RETAINER (CONSISTENT)	NECESSARY	90.70	66.20
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT DAMAGED	352.80	-
1	FRONT BUMPER INNER SPONGE (CONSISTENT)	NOT DAMAGED	100.70	-
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	NOT DAMAGED	322.10	-
1	FRONT BUMPER TOW COVER (CONSISTENT)	NOT DAMAGED	25.10	-
1	FRONT CHROME GRILLE (CONSISTENT)	NOT DAMAGED	1,335.80	-
1	FRONT CHROME GRILLE (CONSISTENT)	NOT DAMAGED	78.10	-
1	RH HEADLAMP ASSY (CONSISTENT)	BROKEN	3,525.10	2,760.00
1	LH HEADLAMP ASSY (CONSISTENT)	NOT DAMAGED	3,525.10	-
1	FRONT BUMPER LOWER COVER (CONSISTENT)	NOT DAMAGED	272.30	-
	LESS 25% DISCOUNT		-2,829.08	-946.85
			8,487.22	2,840.55
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	70.00	30.00
	FRONT NUMBER PLATE (SN) (CONSISTENT)	NOT DAMAGED	70.00	-
			140.00	30.00
	LABOUR			
	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING ,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS.		800.00	200.00
	SPRAY PAINTING ON AFFECTED PANELS.		700.00	200.00
	CHECK WIRING AND LIGHTING SYSTEM.		80.00	30.00
	APPLY RUST COATING ON AFFECTED AREAS .	NOT NECESSARY	50.00	-
	REFOCUS AND ADJUST HEADLAMP ASSY.	NOT NECESSARY	50.00	-
			1,680.00	430.00
	GRAND TOTAL		10,307.22	3,300.55

Report Ref No. CC4/ASM21004366/Bga3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,650.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM21004366/Bga3q2

LIM TEOW GUAN

Automotive Assessor

moli

HO LEONG CHUAN

Automotive Assessor