

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004367/R1QF3E2

Date: 06/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993660
Claimant Vehicle No : YN3847J **Insured Vehicle No :** SLC487X
Date of Loss: 17/03/2021 Nature of Claim: TP Claim No: 3182609878SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN3847J**
Make & Model: MITSUBISHI FM65FM1RDEA, 7.5 D (M) Engine No: 6M60172627
Reg. Date: 20/03/2013 (Man. Year: 2012) Chassis No: FM65FMA10008
Colour: Red Odometer: 324550 km
Engine Capacity: 7545 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7/7 mm
Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/04/2021
Date Inspected: 07/04/2021 Inspected At: RIO LOGISTICS (S) PTE LTD (HQ)
Estimated Period of Repair: 3.0 days No. 21, Pandan Avenue, #04-A
Singapore 609388

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	0.00 F	*- F
2	1		*FRT LH HEADLAMP ASSY COVER	Cracked	0.00 F	*- F
3	1		*FRT STEP PANEL	Scratched	0.00 F	*- F
4	1		*FRT STEP PANEL INNER GARNISH	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >