



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 9764M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT HEADLAMP O/S	CRACKED	763.80	763.80
1	FRONT BUMPER	TO REPAIR SEE LABOUR	498.20	-
1	FRONT BUMPER SIDE RETAINER-O/S	NOT NECESSARY	32.00	-
1	FRONT BUMPER FOG LAMP COVER-O/S	NOT NECESSARY	78.20	-
	LESS 20% DISCOUNT		-274.44	-152.76
			1,097.76	611.04
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		750.00	250.00
	CHECK WIRING.		60.00	20.00
	RUST PROOFING.	NOT NECESSARY	60.00	-
	TO SPRAY PAINT.		480.00	200.00
			1,350.00	470.00
	<b>GRAND TOTAL</b>		<b>2,447.76</b>	<b>1,081.04</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>850.00</b>

Report Ref No. CS/AGI21004370/Utf3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.