

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: ishareauto@gmail.com



DATE : 05.04.21

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : PA7942R
MODEL : TOYOTA HIACE
DATE OF ACCIDENT : 28.03.21
TIME OF ACCIDENT : 07:25HRS

KDH 2230004250

Asher

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	DASHBOARD <i>new</i>	1	\$ 969.90	\$ 969.90
2	DASHBOARD SIDE LOWER COVER GARNISH RH <i>new</i>	1	\$ 312.10	\$ 312.10
3	DASHBOARD CENTER COVER GARNISH <i>new</i>	1	\$ 426.20	\$ 426.20
4	REAR BUMPER <i>new</i>	1	\$ 436.10	\$ 436.10
5	REAR BUMPER BRACKET <i>new</i>	4	\$ 21.80	\$ 87.20
6	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 55.00	\$ 110.00
7	TAIL LAMP <i>LH cut, RH new</i>	2	\$ 390.00	\$ 780.00
8	TAILGATE <i>Distorted</i>	1	\$ 2,054.30	\$ 2,054.30
9	TAILGATE LOGO <i>new</i>	1	\$ 75.20	\$ 75.20
10	TAILGATE CENTER MOULDING (CHROME) <i>new</i>	1	\$ 674.80	\$ 674.80
11	TAILGATE CORNER INNER GARNISH <i>new</i>	2	\$ 36.20	\$ 72.40
12	TAILGATE STOPPER <i>new</i>	1	\$ 28.00	\$ 28.00
13	TAILGATE INNER BOARD <i>new</i>	1	\$ 271.80	\$ 271.80
14	TAILGATE WEATHERSTRIP <i>new</i>	1	\$ 329.50	\$ 329.50
15	TAILGATE WEATHERSTRIP PROTECTOR <i>new</i>	1	\$ 368.20	\$ 368.20
16	TAILGATE INNER LOCK <i>Damaged</i>	1	\$ 425.60	\$ 425.60
17	TAILGATE LOWER LOCK <i>new</i>	1	\$ 45.20	\$ 45.20
18	TAILGATE DAMPER <i>new</i>	2	\$ 127.40	\$ 254.80
19	REAR END PANEL (INNER) <i>new</i>	1	\$ 1,043.20	\$ 1,043.20
20	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 597.00	\$ 597.00
21	REAR END PANEL (EXTEND) RH <i>Dented</i>	1	\$ 349.10	\$ 349.10

TOTAL PRICE \$ 9,710.60
LESS 25% \$ 2,427.65
SUB TOTAL PRICE \$ 7,282.95

6025
4518.75

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : PA7942R
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 28.03.21
 TIME OF ACCIDENT : 07:25HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	DASHBOARD CLIP (SET) <i>Neu</i>	1	\$ 150.00	\$ 150.00 <i>x</i>
2	DASHBOARD SIDE LOWER COVER GARNISH CLIP RH (SET) <i>AP neu</i>	1	\$ 80.00	\$ 80.00 <i>x</i>
3	DASHBOARD CENTER COVER GARNISH CLIP (SET) <i>neu</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
4	REAR NUMBER PLATE <i>Neu</i>	1	\$ 80.00	\$ 80.00 <i>x</i>
5	REAR BUMPER CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
6	TAIL LAMP CLIP (SET) <i>neu</i>	1	\$ 60.00	\$ 60.00 <i>20</i>
7	TAILLAMP LOWER GARNISH CLIP (SET) <i>Neu</i>	1	\$ 40.00	\$ 40.00 <i>x</i>
8	TAILGATE SEALANT <i>Neu</i>	1	\$ 120.00	\$ 120.00 <i>x</i>
9	TAILGATE CENTER MOULDING 'EMERGENCY DOOR PULL TOPEN' STICKER <i>Neu</i>	1	\$ 50.00	\$ 50.00 <i>x</i>
10	TAILGATE CENTER MOULDING (CHROME) CLIP (SET) <i>neu</i>	1	\$ 60.00	\$ 60.00 <i>10</i>
11	TAILGATE INNER BOARD CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
12	TAILGATE WINDSCREEN SEALANT <i>3 neu</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
13	TAILGATE WINDSCREEN INNER SEAL <i>neu</i>	1	\$ 60.00	\$ 60.00 <i>40</i>
14	TAILGATE STICKER '70KM/H' <i>Neu</i>	1	\$ 30.00	\$ 30.00 <i>15</i>
15	REAR END PANEL (OUTER) SEALANT <i>Neu</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
16	REAR END PANEL (EXTEND) SEALANT RH <i>Neu</i>	1	\$ 80.00	\$ 80.00 <i>x</i>
17	REAR FLOOR TOP COVER BOARD (SPECIAL TYPE) <i>MT neu</i>	1	\$ 650.00	\$ 650.00 <i>x</i>
18	REAR FLOOR PANEL MAT (SPECIAL TYPE) <i>Neu</i>	1	\$ 650.00	\$ 650.00 <i>x</i>
19	REVERSE SENSOR (SET) <i>Dang</i>	1	\$ 220.00	\$ 220.00 <i>200</i>
20	REVERSE CAMERA <i>Neu</i>	1	\$ 550.00	\$ 550.00 <i>x</i>

475

TOTAL \$ 3,350.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 1,600.00	1,600.00 <i>800</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	1,600.00 <i>800</i>
3	WIRING, BULB CHECKING	\$ 150.00	150.00 <i>30</i>
4	REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING	\$ 680.00	680.00 <i>150</i>
5	TRANSFER TAILGATE MECHAISM	\$ 80.00	80.00 <i>✓</i>
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	120.00 <i>✓</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : PA7942R
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 28.03.21
 TIME OF ACCIDENT : 07:25HRS

7	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
8	REAR CHASSIS ALIGHMENT	\$ 250.00	X
9	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	50
10	REMOVE AND REFIX REAR REVERSE CAMERA	\$ 80.00	50
11	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	50
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 5,020.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,632.95
 TOTAL LABOUR COST : \$ 5,020.00
 TOTAL REPAIR COST : \$ 15,652.95

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE

HP : 9856 4815

2130

Adrian Lj
 L/S 05/04/21.

06 Days ✓

total: 7123.75

L/S: 5.7K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: