

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004378/BQF3E2

Date: 25/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070162533		
Claimant Vehicle No :	FBN7135B	Insured Vehicle No :	SKQ4529X		
Date of Loss:	30/03/2021	Nature of Claim:	TP	Claim No:	8114722906SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN7135B	Engine No:	MA32M5001492
Make & Model:	PIAGGIO VESPA GTS 150, 155cc ABS	Chassis No:	ZAPMA320000001526
Reg. Date:	29/11/2018 (Man. Year: 2018)	Odometer:	44871 km
Colour:	Grey		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70/12	Rear Tyre Size:	130/70/12
Front Left Side:	Pirelli 4 mm	Rear Left Side:	MITAS 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/04/2021		
Date Inspected:	07/04/2021	Inspected At:	V MAPS MOTOR (HQ) 10 KAKI BUKIT RD 2 #01-36 Singapore 417868
Estimated Period of Repair:	4.0 days		

Adjuster: Lim Teow Guan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$5,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*PAIR FRONT WING MIRROR	Missing	0.00 F	*- F
3	1		*CLUTCH LEVER	Cut	0.00 F	*- F
4	1		*FRT FAIRING GARNISH	Cut	0.00 F	*- F
5	1		*FRT WHEEL FENDER	Cut	0.00 F	*- F
6	1		*FRT FAIRING	Repair	0.00 F	*- F
7	1		*MAIN STAND	Cut	0.00 F	*- F
8	1		*REAR FENDER UPPER	Cut	0.00 F	*- F
9	1		*REAR NUMBER PLATE	Broken	0.00 F	*- F
10	1		*REAR BOX	Cut	0.00 F	*- F
11	1		*REAR EMBLEM	Missing	0.00 F	*- F
12	1		*LEFT REAR FENDER LOWER SIDE	Dented	0.00 F	*- F
13	1		*REAR MUD FLAP	Bent	0.00 F	*- F
14	1		*REAR NUMBER PLATE	Broken	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >