LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004380/QVF3E2

Date: 20/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100494081

Claimant Vehicle

No: SLL1518L Insured Vehicle No: SLJ5198K

Date of Loss: 04/04/2021 Nature of Claim: TP Claim No: 6935118684SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL1518L

 Make & Model:
 HONDA SHUTTLE, 1.5 G CVT (A)
 Engine No:
 L15B5001358

 Reg. Date:
 15/02/2017 (Man. Year: 2016)
 Chassis No:
 GK81101138

 Colour:
 Red
 Odometer:
 43894 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm
Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/04/2021

Yap Auto Service (HQ)

Date Inspected: 07/04/2021 Inspected At: Blk 9004 Tampines St 93, #01-78

Singaporo 528838

Singapore 528838

Estimated Period of Repair: 1.0 days

Adjuster: OI SUN PIN Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT RH DOOR	Repair	0.00 F	*- F
2	1	*FRT RH DOOR WING MIRROR	Crumpled	0.00 F	*- F
3 F=Fr:	1 anchise part.	*FRT RH DOOR GLASS OUTER MOULDING	Scratched	0.00 F	*- F
	anomoo part.		Total Parts (S\$)	0.00	0.00
		Report was unsubmitted during t	his print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >