

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG21004383/KRS3Q2

**Date:** 28/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070175958

**Claimant**  
**Vehicle No :** SMV5927Z **Insured Vehicle No :** SMX3368P

Date of Loss: 05/04/2021 Nature of Claim: TP Claim No: 3542846167SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMV5927Z</b>		
Make & Model:	HONDA FIT, 1.3 (A)	Engine No:	L13B3939390
Reg. Date:	08/10/2020 (Man. Year: 2019)	Chassis No:	GK33424900
Colour:	Metallic Grey	Odometer:	8152 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,735.20	1,032.14	703.06	40.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	700.00	900.00	56.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,335.20</b>	<b>1,732.14</b>	<b>1,603.06</b>	<b>48.06</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,350.00</b>		
<b>(\$\$)</b>	3,335.20	1,350.00	1,985.20	59.52
<b>+ GST 7.00/7.00% (\$\$)</b>	233.46	94.50	138.96	59.52
<b>Nett Amount (\$\$)</b>	<b>3,568.66</b>	<b>1,444.50</b>	<b>2,124.16</b>	<b>59.52</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 06/04/2021

Date Inspected: 07/04/2021 Inspected At:

Hui Yang Motor Pte Ltd (HQ)  
176 Sin Ming Drive #04-02, Sin Ming  
AutoCare  
Singapore 575721

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG

**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH TAILLAMP	Mtg Cracked	357.40 FL	*272.80 FL
2	1		*REAR RH TAILLAMP LOWER BRACKET	Serviceable	75.50 FL	*- FL
3	1		*REAR BUMPER	Buckled	896.50 FL	*592.77 FL
4	1		*REAR BUMPER RH SIDE RETAINER	Distorted	39.10 FL	*39.10 FL
5	1		*REAR BUMPER RH SIDE GARNISH	Serviceable	125.50 FL	*- FL
6	1		*REAR BUMPER CENTRE GARNISH	Serviceable	189.50 FL	*- FL
7	1		*REAR BUMPER RH INNER SHIELD	Distorted	85.50 FL	*85.50 FL
8	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
9	1		*SET REAR PARKING SENSOR	Dented / Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,099.00</b>	<b>1,240.17</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	<b>363.80</b>	<b>208.03</b>
<b>Total Parts (\$)</b>	<b>1,735.20</b>	<b>1,032.14</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	800.00	300.00
2	LABOUR CHARGES	New	800.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>1,600.00</b>	<b>700.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**