

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004385/R1GS3Q2
Date: 05/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100397091
Claimant Vehicle No :	SME9913B	Insured Vehicle No :	SJA6286D
Date of Loss:	04/04/2021	Nature of Claim:	TP
		Claim No:	1552528180SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME9913B	Engine No:	LEB1432615
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Chassis No:	GP51327757
Reg. Date:	24/10/2018 (Man. Year: 2018)	Odometer:	163624 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,840.00	3,494.00	7,346.00	67.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	710.00	3,530.00	83.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,080.00	4,204.00	10,876.00	72.12
Approved Total (Overridden) (S\$)		3,350.00		

Nett Amount (S\$)	15,080.00	3,350.00	11,730.00	77.79
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
Nett Liability (S\$)		3,910.00		

INSPECTION

Date of Assignment: 06/04/2021

Date Inspected: 12/04/2021

Estimated Period of Repair: 3.0 days

Inspected At:

8 Kaki Bukit Avenue 4 #05-23

Repairer:Xin Yun Auto Private Limited (HQ)

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Dented	880.00 F	*880.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Broken	180.00 F	*180.00 FL
3	2		*FRONT BUMPER BRACKET	Serviceable	190.00 F	*- FL
4	1		*FRONT PANEL LOWER SUPPORT METAL PIECE	Bent	295.00 F	*295.00 FL
5	1		*FRONT CENTER CHROME	Broken	785.00 F	*450.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Broken	350.00 F	*350.00 FL
7	1		*FRONT LIGHT LEFT	Broken	880.00 F	*880.00 FL
8	1		*FRONT LIGHT RIGHT	Broken	880.00 F	*880.00 FL
9	1		*FRONT LIGHT SUPPORT BRACKET (RH)	Broken	195.00 F	*195.00 FL
10	1		*FRONT LIGHT SUPPORT BRACKET (LH)	Broken	195.00 F	*195.00 FL
11	1		*FRONT BONNET	Repair	1,800.00 F	*- FL
12	1		*BONNET INNER GARNISH SEAL	Not Necessary	220.00 F	*- FL
13	1		*BONNET LOCK ASSY WITH SENSOR	Not Necessary	325.00 F	*- FL
14	1		*HORN	Not Necessary	105.00 F	*- FL
15	1		*RADIATOR	Not Necessary	950.00 F	*- FL
16	1		*RADIATOR FRAME	Not Necessary	880.00 F	*- FL
17	1		*REINFORCEMENT	Not Necessary	380.00 F	*- FL
18	10		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
19	1		*FRONT BUMPER LOWER GRILLE CLIPS (6 PCS)	Necessary	50.00 FS	*20.00 FS
20	8		*FRONT BONNET INNER BOARD CLIPS	Not Necessary	60.00 FS	*- FS
21	6		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
22	8		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
23	1		*COOLANT AND GAS	Not Necessary	60.00 FS	*- FS
24	2		*FRONT BUMPER 2 PARKING SENSOR	Not Necessary	980.00 FS	*- FS
25	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,840.00	4,355.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	861.00
Total Parts (\$\$)	10,840.00	3,494.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS	New	1,500.00	250.00
2	LABOUR PUTTY AND SPRAY PAINTING FRONT PORTION	New	1,500.00	400.00
3	LABOUR TO APPLY ANTI RUST PROOFING TO FRONT LEFT AFFECTED AREA	New	150.00	30.00
4	LABOUR TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	80.00	30.00
5	LABOUR TO REMOVE & INSTALL FRONT BONNET LOCK MECHANISM	New	100.00	0.00
6	LABOUR TO REMOVE AND INSTALL AND ADJUST THE DOOR ALIGNMENT	New	120.00	0.00
7	LABOUR TO CHECK AND INSTALL AIRCON RELATED SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS AND CHECK LEAKAGE	New	120.00	0.00
8	LABOUR TO CHECK ,REMOVE AND REPLACE AIRCON RELATED RADIATOR ,HIGH PRESURE AND LOW PRESSURE HOSE ,CHECK AIR-CON ,TOP UP GAS ETC	New	150.00	0.00
9	LABOUR TO REMOVE AND INSTALL FRONT PARKING SENSOR AND INNER COOLER ASSY	New	150.00	0.00
10	TO BALANCE FRONT WHEEL	New	100.00	0.00
11	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
12	TO CONDUCT CHASSIS ALIGNMENT	New	150.00	0.00
Gross Labour Cost (S\$)			4,240.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >