

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte L 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 792S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	MOULDING BODY, RH (DISC 25%)	DEFORMED	673.60	505.20
1	DOOR RR/RH (DISC 25%)	CRUMPLED	954.50	715.88
1	WHEEL HUB REAR (DISC 25%)	JAMMED	489.40	367.05
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	ADVERTISEMENT STICKER (SN)	NECESSARY	742.20	593.76
1	TYRE	SERVICEABLE	126.74	-
1	WHEEL HUB REAR	SERVICEABLE	489.40	-
1	PIXEL STICKER	SERVICEABLE	60.00	-
1	BUMPER REAR	SERVICEABLE	458.60	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	FENDER RR/RH	TO REPAIR SEE LABOUR	766.80	-
1	WHEEL DISC	TO REPAIR SEE LABOUR	1,484.20	-
			6,429.64	2,271.29
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FENDER RR/RH AND WHEEL DISC.		676.00	300.00
	SPRAY PAINT.		1,494.00	540.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO RMEOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	40.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO TRANSFER DOOR MECHANISM.		120.00	60.00
			2,870.00	960.00
	GRAND TOTAL		9,299.64	3,231.29

Report Ref No. CS/SMO21004387/QKtf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,900.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO21004387/QKtf3e2

KONG SENG CHEONG

Licensed Appraiser