

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21004388/EVF3E2

**Date:** 07/05/2021

### REFERENCE

Insured/Claimant:	OLIVIA HWAI FANG LOH MRS OLIVIA HWAI FANG LOH	Policy No:	1800012223-02		
Date of Loss:	31/03/2021	Nature of Claim:	OD	Claim No:	7695991294SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW3478Y	Engine No:	G4FGHH691742
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAFJ411MJ5761800
Reg. Date:	08/02/2018 (Man. Year: 2017)	Odometer:	32406 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$65,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,574.80	1,484.00	1,090.80	42.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,390.00	3,650.00	1,740.00	32.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,964.80</b>	<b>5,134.00</b>	<b>2,830.80</b>	<b>35.54</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>7,664.80</b>	<b>4,834.00</b>	<b>2,830.80</b>	<b>36.93</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>536.54</b>	<b>338.38</b>	<b>198.16</b>	<b>36.93</b>
<b>Nett Amount (S\$)</b>	<b>8,201.34</b>	<b>5,172.38</b>	<b>3,028.96</b>	<b>36.93</b>

### INSPECTION

Date of Assignment:	06/04/2021	
Date Inspected:	07/04/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	9.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPORT RIM	Cut	380.00 FS	*380.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*PANEL ASSY-QUARTER OUTER, LH	Dented	1,213.00 FL	*1,213.00 FL
4	1		*COVER-RR BUMPER	Repair	688.00 FL	*- FL
5	1		*BRACKET-RR BUMPER SIDE MTG, LH	Not Necessary	29.00 FL	*- FL
6	1		*FILM-ANTI CHIPPG LH	Necessary	27.00 FL	*27.00 FL
7	1		*GUARD ASSY-REAR WHEEL, LH	Not Necessary	75.00 FL	*- FL
8	1		*GLASS ASSY-REAR WINDOW	Not Necessary	534.00 FL	*- FL
9	2		*STOPPER-RR WINDOW GLASS	Necessary	8.00 FL	*8.00 FL
10	10		*PAD-WINDSHIELD GLASS	Necessary	20.00 FL	*20.00 FL
11	1		*MOULDING-REAR WINDOW GLASS (Supplementary)	Necessary	27.00 FL	*27.00 FL
12	2		*STOPPER-RR WINDOW GLASS (Supplementary)	Necessary	8.00 FL	*8.00 FL
13	1		*CHANNEL ASSY-REAR DOOR DIVISION (Supplementary)	Cut	52.00 FL	*52.00 FL
					<b>Sub Total (\$\$)</b>	<b>3,111.00 1,755.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>536.20 271.00</b>
					<b>Total Parts (\$\$)</b>	<b>2,574.80 1,484.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE REAR LH FENDER, REAR BUMPER & AFFECTED AREA. REPAIR ON REAR LH DOOR	New	2,400.00	1,200.00
2	PAINT WORK ON REAR LH DOOR, REAR LH FENDER & REAR BUMPER	New	1,050.00	1,050.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	60.00
4	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
5	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR	New	120.00	120.00
6	REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR	New	400.00	400.00
7	REMOVE & INSTALL REAR WINDSCREEN GLASS	New	240.00	240.00
8	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
9	PERFORM RUST PREVENTION	New	80.00	40.00
10	TO APPLY BODY SEALANT ON AFFECTED AREA	New	80.00	40.00
11	REPLACE REAR UNDERCARRIAGE	New	400.00	0.00
12	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
13	TO TRANSFER REAR LH RIM INCLUDING BALANCING	New	30.00	30.00
14	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
15	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,390.00</b>	<b>3,650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >