

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21004391/AGS3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900236140
Claimant Vehicle No :	SJM8430C	Insured Vehicle No :	SKN376L
Date of Loss:	01/04/2021	Nature of Claim:	TP
		Claim No:	3226840549SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM8430C		
Make & Model:	LEXUS IS, 2.5 250 STD FL (A)	Engine No:	4GR0530199
Reg. Date:	19/01/2009 (Man. Year: 2008)	Chassis No:	JTHBK262405092058
Colour:	Grey	Odometer:	158319 km
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,260.86	1,584.40	2,676.46	62.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	810.00	500.00	38.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,570.86	2,394.40	3,176.46	57.02
Approved Total (Overridden) (S\$)		1,900.00		

(S\$)	5,570.86	1,900.00	3,670.86	65.89
+ GST 7.00/7.00% (S\$)	389.96	133.00	256.96	65.89
Nett Amount (S\$)	5,960.82	2,033.00	3,927.82	65.89
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
Nett Liability (S\$)		2,483.00		

INSPECTION

Date of Assignment: 05/04/2021

Date Inspected: 05/04/2021

Estimated Period of Repair: 3.0 days

Inspected At:

J-mart Motor Pte Ltd (HQ)
Blk 5 Defu Lane 10, #01-578
Singapore 539186

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	980.00 FL	*980.00 FL
2	1		*REAR BUMPER RETAINER LONG	Damaged	135.00 FL	*135.00 FL
3	1		*REAR BUMPER RETAINER SHORT	Not Necessary	80.00 FL	*- FL
4	1		*REAR BUMPER RH REFLECTOR	Not Necessary	120.00 FL	*- FL
5	5		*REAR BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
6	1		*REAR RH FENDER	Repair	1,760.00 FL	*- FL
7	1		*REAR RH FENDER INNER SHIELD	Torn	176.00 FL	*176.00 FL
8	1		*RH TAILLAMP	Not Necessary	569.40 FL	*- FL
9	1		*REAR RH TYRE	Not Necessary	400.00 FS	*- FS
10	1		*REAR RH RIM	Cut	400.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,645.40	1,716.00
- List Item Discount on L Items 10.00/10.00% (S\$)	384.54	131.60
Total Parts (S\$)	4,260.86	1,584.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	300.00
2	SPRAY PAINTING	New	600.00	400.00
3	WIRING	New	30.00	30.00
4	ALIGNMENT	New	80.00	80.00
Gross Labour Cost (S\$)			1,310.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >