

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21004396/R1QCE2

Date: 06/09/2021

REFERENCE

Insured/Claimant:	SIM MAY LING AMY	Policy No:	2070119748		
Date of Loss:	03/04/2021	Nature of Claim:	OD	Claim No:	1835940877SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB1656Z	Engine No:	CZD895498
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF30L1107533
Reg. Date:	17/08/2020 (Man. Year: 2020)	Odometer:	3123 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$139,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	53,973.00	31,453.12	22,519.88	41.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,284.00	12,474.00	7,810.00	38.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	74,257.00	43,927.12	30,329.88	40.84
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	73,857.00	43,527.12	30,329.88	41.07
+ GST 7.00/7.00% (S\$)	5,169.99	3,046.90	2,123.09	41.07
Nett Amount (S\$)	79,026.99	46,574.02	32,452.97	41.07

INSPECTION

Date of Assignment:	07/04/2021		
Date Inspected:	06/04/2021	Inspected At:	24 Benoi Sector Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	18.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BUMPER	Torn	2,161.00 FS	*1,728.40 FS
2	1		*FRONT BUMPER CLOSING ELEMENT	N/S Serviceable / O/S Cracked	118.00 FS	*46.64 FS
3	1		*FRONT BUMPER GRILLE - CENTER	Cracked	217.00 FS	*173.20 FS
4	1		*FRONT BUMPER LOWER GRILLE CENTRE COVER	Serviceable	51.00 FS	*- FS
5	1		*FRONT BUMPER LOWER GRILLE - LH / RH	N/S Serviceable / O/S Cracked	220.00 FS	*88.00 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Serviceable	190.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Scratched	383.00 FS	*306.40 FS
8	1		*FRONT BUMPER BRACKET	Serviceable	21.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	O/S Missing /N/S Serviceable	306.00 FS	*244.00 FS
10	1		*FRONT RADIATOR GRILLE	Cracked	1,433.00 FS	*1,146.40 FS
11	1		*FRONT RADIATOR STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
12	1		*FRONT RADIATOR COVER CAP	Missing	45.00 FS	*35.60 FS
13	1		*FRONT RADIATOR BRACKET	Cracked	41.00 FS	*32.48 FS
14	1		*FRONT CAMERA	Serviceable	1,141.00 FS	*- FS
15	1		*SET FRONT BUMPER WIRING	Cracked	676.00 FS	*540.80 FS
16	1		*FRONT BUMPER CARRIER	Bent	916.00 FS	*732.40 FS
17	1		*FRONT BUMPER GUIDE SECTION - LH / RH	Serviceable	78.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Deformed	123.00 FS	*98.00 FS
19	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	102.00 FS	*81.60 FS
20	1		*AIR CONDITIONER STICKER LABEL	Necessary	8.00 FS	*5.68 FS
21	4		*FRONT PARKING AID SENSOR	Not Working (2Pcs Only)	976.00 FS	*390.24 FS
22	4		*FRONT PARKING AID SENSOR SEAL RING	Necessary	14.00 FS	*11.20 FS
23	1		*SIGNAL HIGH TONE HORN - LH	Serviceable	137.00 FS	*- FS
24	1		*SIGNAL LOW TONE HORN - RH	Serviceable	130.00 FS	*- FS
25	1		*SIGNAL HORN SPRING SHACKLE - LH / RH	O/S Bent / N/S Serviceable	44.00 FS	*17.04 FS
26	1		*FRONT FENDER - LH / RH	O/S Bent / N/S Serviceable	2,572.00 FS	*1,028.80 FS
27	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	-
28	2		*FRONT FENDER BRACE - LH / RH	Serviceable	176.00 FS	*- FS
29	1		*FRONT FENDER BRACKET - LH / RH	O/S Bent / N/S Serviceable	64.00 FS	*24.88 FS
30	1		*FRONT BONNET	Buckled	3,508.00 FS	*2,806.40 FS
31	2		*FRONT BONNET HINGE - LH / RH	Bent	146.00 FS	*115.52 FS
32	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	296.00 FS	*- FS
33	2		*FRONT BONNET STRIKER - LH / RH	Bent	220.00 FS	*175.20 FS
34	1		*FRONT BONNET SOUND ABS	Not Necessary	219.00 FS	*- FS
35	1		*FRONT BONNET IMPACT PROTECTION	Cracked	28.00 FS	*21.84 FS
36	2		*FRONT BONNET HINGE COVER - LH / RH	Serviceable	82.00 FS	-
37	1		*FRONT PLENUM CHAMBER COVER	Cut	129.00 FS	*103.20 FS
38	1		*FRONT BONNET BOWDEN CABLE	Cut	58.00 FS	*46.00 FS
39	2		*FRONT BONNET LOCK	Bent	427.00 FS	*341.60 FS
40	1		*FRONT BONNET RELEASE ELEMENT	Bent	58.00 FS	*46.00 FS
41	1		*FRONT BONNET RELEASE LEVER	Scratched	14.00 FS	*11.20 FS
42	1		*FRONT BONNET RELEASE CABLE COVER	Missing	10.00 FS	*7.60 FS
43	1		*FRONT BONNET LOCK CABLE	Serviceable	74.00 FS	*- FS
44	1		*FRONT BONNET STRUT	Serviceable	104.00 FS	*- FS
45	2		*HEADLIGHT MOUNTING BEAM - LH / RH	Cracked	236.00 FS	*188.80 FS
46	2		*HEADLIGHT - LH / RH	Broken	11,178.00 FS	*8,942.40 FS
47	1		*HEADLIGHT HEAT SINK	Serviceable	781.00 FS	*- FS
48	1		*HEADLIGHT POWER MODULE	Damaged	758.00 FS	*606.40 FS
49	1		*HEADLIGHT HOSE - RH	Serviceable	24.00 FS	*- FS
50	2		*HEADLIGHT LIFT CYLINDER - LH / RH	Serviceable	420.00 FS	*- FS
51	1		*HEADLIGHT LIFT CYLINDER HOSE	Cut	80.00 FS	*63.44 FS
52	1		*FRONT RADIATOR LOCK CARRIER	Cracked	1,272.00 FS	*1,017.60 FS
53	1		*A/C CONDENSER	Bent	551.00 FS	*440.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*A/C REFRIGERANT LINE SEAL RING	Necessary	10.00 FS	*7.28 FS
55	1		*EXPANSION VALVE O-RING	Necessary	7.00 FS	*5.52 FS
56	1		*REFRIGERANT LINE LONG	Bent	330.00 FS	*264.00 FS
57	1		*REFRIGERANT LINE SHORT	Bent	337.00 FS	*269.60 FS
58	1		*REFRIGERANT LINE DUAL CLIP	Not Necessary	30.00 FS	*- FS
59	1		*TEMPERATURE SENSOR	Serviceable	59.00 FS	*- FS
60	1		*TEMPERATURE SENSOR HOLDER	Serviceable	7.00 FS	*- FS
61	1		*ADDITIONAL RADIATOR COOLER	Bent	920.00 FS	*736.00 FS
62	1		*RADIATOR COOLER	Bent	1,035.00 FS	*828.00 FS
63	4		*RADIATOR COOLANT	Necessary	179.00 FS	*143.04 FS
64	2		*RADIATOR MOUNT BRACKET	Cracked	82.00 FS	*65.28 FS
65	2		*RADIATOR BUSH	Necessary	19.00 FS	*15.04 FS
66	1		*RADIATOR FAN	Cracked	1,529.00 FS	*1,223.20 FS
67	2		*RADIATOR AIR BAFFLE GUIDE - LH / RH	Torn	76.00 FS	*59.52 FS
68	1		*RADIATOR AIR BAFFLE GUIDE - UPPER / LOWER	UpperCracked/LowerNotNecessary	84.00 FS	*33.04 FS
69	1		*RADIATOR INTAKE AIR DUCT	Cracked	29.00 FS	*22.72 FS
70	1		*INTAKE AIR INLET COVER	Cracked	56.00 FS	*44.48 FS
71	1		*INTAKE AIR GUIDE SHORT	Cracked	20.00 FS	*15.36 FS
72	1		*WATER DRAINAGE HOSE	Missing	21.00 FS	*16.16 FS
73	1		*INTAKE AIR GUIDE LONG	Cracked	34.00 FS	*26.80 FS
74	1		*AIR FILTER	Deformed	239.00 FS	*191.20 FS
75	1		*INTAKE AIR DUCT	Deformed	47.00 FS	*37.52 FS
76	1		*INTAKE MANIFOLD	Serviceable	121.00 FS	*- FS
77	1		*INTAKE CONNECTION	Cracked	610.00 FS	*488.00 FS
78	1		*AIR COOLER	Bent	775.00 FS	*619.60 FS
79	1		*THROTTLE VALVE ADAPTER	Cracked	824.00 FS	*659.20 FS
80	1		*INTAKE RETAINING BAR	Not Necessary	15.00 FS	-
81	1		*INTAKE PRESSURE SENSOR	Cracked	194.00 FS	*155.20 FS
82	1		*ALTERNATOR	Serviceable	2,499.00 FS	*- FS
83	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	536.00 FS	*428.80 FS
84	1		*FRONT WINDOW OUTER SLOT SEAL - RH	Cut	224.00 FS	*179.20 FS
85	1		*FRONT WINDSCREEN	Cracked	1,121.00 FS	*896.80 FS
86	1		*RAIN SENSOR GEL FOIL	Necessary	137.00 FS	*109.20 FS
87	1		*RAIN SENSOR RETAINING SPRING	Not Necessary	21.00 FS	*- FS
88	1		*FRONT NOISE INSULATION	Serviceable	397.00 FS	*- FS
89	1		*EXHAUST MANIFOLD	Serviceable	4,871.00 FS	*- FS
90	1		*EXHAUST MANIFOLD SEAL	Not Necessary	15.00 FS	*- FS
91	4		*EXHAUST MANIFOLD THREADED PIN	Not Necessary	23.00 FS	*- FS
92	2		*OIL FEED SEAL RING	Not Necessary	11.00 FS	*- FS
93	2		*OIL TUBE SEAL RING	Not Necessary	46.00 FS	*- FS
94	2		*INTAKE PIPE GASKET	Not Necessary	27.00 FS	*- FS
95	1		*PRESSURE PIPE SEAL	Not Necessary	18.00 FS	*- FS
96	1		*FRONT NUMBER PLATE	Bent	60.00 FS	*60.00 FS
97	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
98	1		*SUNDRIES	Necessary	350.00 FS	*227.60 FS
99	1		*FRONT CAMARE SECURING PLATE (Supplementary)	Cracked	33.00 FS	*26.16 FS
100	1		*FRONT FENDER TOP SIDE MEMBER - RH (Supplementary)	Bent	431.00 FS	*344.80 FS
101	1		*FRONT FENDER TOP CLOSING ELEMENT - RH (Supplementary)	Serviceable	357.00 FS	*- FS
102	1		*COOLANT PIPE QUICK ACTING COUPLING - UPPER (Supplementary)	Cracked	18.00 FS	*13.76 FS
103	1		*REFRIGERANT LINE (A/C COMPRESSOR->CUT-OFF POINT) (Supplementary)	Bent	337.00 FS	*269.60 FS
104	1		*REFRIGERANT LINE BRACKET (Supplementary)	Bent	27.00 FS	*20.88 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
105	1		*PRESSURE PIPE (Supplementary)	Bent	363.00 FS	*290.00 FS
106	1		*INTAKE HOSE CLAMPS (Supplementary)	Not Necessary	59.00 FS	*- FS
107	1		*ACRYLIC SEALER (Supplementary)	Necessary	180.00 FS	*180.00 FS
108	1		*CAVITY WAX (Supplementary)	Necessary	140.00 FS	*140.00 FS
109	1		*STONE CHIP (Supplementary)	Not Necessary	180.00 FS	*- FS
110	1		*METAL FILLER POWDER (Supplementary)	Necessary	280.00 FS	*280.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 53,973.00 31,453.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,700.00	1,700.00
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	400.00	360.00
4	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNITS AND POWER MODULES	New	800.00	500.00
5	TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
6	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
7	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	400.00
8	TO REMOVE AND RENEW FRONT WINDSCREEN FOIL SENSOR AND RESET SYSTEM (* Check)	New	300.00	0.00
9	TO RENEW EXHAUST TURBO CHARGER AND OTHER ENGINE COMPONENTS	New	480.00	480.00
10	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,300.00	3,000.00
11	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, RHS FRONT DOOR	New	5,300.00	2,360.00
12	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
13	TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT AND CLOSING ELEMENT (Supplementary)	New	2,000.00	1,500.00
14	TO RESPRAY RHS FRONT FENDER TOP SUPPORT (Supplementary)	New	700.00	550.00
15	TO RENEW AIRCON CONDENSER REFRIGERANT PIPES (Supplementary)	New	280.00	280.00
Gross Labour Cost (S\$)			20,284.00	12,474.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >