

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21004397/AVCN2**Date:** 07/09/2021**REFERENCE**

Insured/Claimant:	PECK JEN JEN	Policy No:	1800097991		
Date of Loss:	03/04/2021	Nature of Claim:	OD	Claim No:	3172055136SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD2020D		
Make & Model:	AUDI TT, COUPE 1.8T (A)	Engine No:	CJS278388
Reg. Date:	23/08/2018 (Man. Year: 2018)	Chassis No:	TRUZZZFV7J1015021
Colour:	Black	Odometer:	50672 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,860.00	8,955.60	8,904.40	49.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	1,972.00	3,150.00	61.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,982.00	10,927.60	12,054.40	52.45
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
(S\$)	21,782.00	9,727.60	12,054.40	55.34
+ GST 7.00/7.00% (S\$)	1,524.74	680.93	843.81	55.34
Nett Amount (S\$)	23,306.74	10,408.53	12,898.21	55.34

INSPECTION

Date of Assignment:	07/04/2021		
Date Inspected:	06/04/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,506.00 FS	*2,004.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	486.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-RH	Broken	111.00 FS	*88.80 FS
4	1		*FRONT BUMPER SECURING STRIP-RH	Not Necessary	43.00 FS	*- FS
5	1		*FRONT BUMPER LOWER GRILLE-CENTRE	Not Necessary	161.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	156.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Cut	217.00 FS	*173.20 FS
8	1		*RADIATOR GRILLE	Not Necessary	1,359.00 FS	*- FS
9	1		*INNER COVER	Not Necessary	65.00 FS	*- FS
10	1		*RADIATOR GRILLE COVER	Not Necessary	107.00 FS	*- FS
11	1		*FRONT BUMPER LOWER COVER-RH	Not Necessary	56.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,084.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER	Cracked	129.00 FS	*103.20 FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	39.00 FS	*- FS
16	1		*FRONT BUMPER PARKING SENSOR (Npa)	Not Necessary	0.00 FS	*- FS
17	4		*SENSOR O RUBBER SEAL	Not Necessary	14.00 FS	*- FS
18	1		*FRONT BUMPER WIRING SET	Not Necessary	577.00 FS	*- FS
19	1		*SIGNAL HORN-RH LOW TONE	Not Necessary	286.00 FS	*- FS
20	1		*LED HEADLIGHT	Cut	7,926.00 FS	*6,340.80 FS
21	1		*HEADLIGHT LIFT CYLINDER-RH	Cracked	159.00 FS	*127.20 FS
22	1		*HEADLIGHT LIFT CYLINDER BRACKET-RH	Damaged	29.00 FS	*23.20 FS
23	1		*WATER HOSE	Not Necessary	77.00 FS	*- FS
24	1		*FRONT FENDER-RH	Not Necessary	1,188.00 FS	*- FS
25	1		*FRONT FENDER ATTACHMENT PARTS-RH	Not Necessary	40.00 FS	*- FS
26	1		*FRONT FENDER BRACKET-RH UPPER	Not Necessary	50.00 FS	*- FS
27	1		*FRONT FENDER BRACKET-CENTRE RH UPPER	Not Necessary	44.00 FS	*- FS
28	1		*FRONT FENDER INNER GARNISH-RH	Not Necessary	170.00 FS	*- FS
29	1		*FRONT FENDER INNER GARNISH ATTACHMENT PARTS-RH	Not Necessary	112.00 FS	*- FS
30	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	117.00 FS	*- FS
31	1		*AIR GUIDE-RH	Not Necessary	35.00 FS	*- FS
32	1		*AIR GUIDE SEAL-RH	Not Necessary	8.00 FS	*- FS
33	1		*SEAL STRIP INSERT-FILLER PIECE	Not Necessary	4.00 FS	*- FS
34	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
35	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
36	1		*FRONT FENDER BRACE-RH	Bent	118.00 FS	*94.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 17,860.00 8,955.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK & TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,122.00	1,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >