



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 8869Y

| Qty   | Description of Parts  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|----------------------|---------------------------|-------------------|
|   | <b><u>REPLACEMENT OF PARTS</u></b>  |                      |                           |                   |
| 1   | SIDE MIRROR RH (WCP)  | CUT                  | 650.00                    | 650.00            |
| 1   | SIDE MIRROR COVER RH (WCP)  | BROKEN               | 250.00                    | 250.00            |
| 1   | SIDE MIRROR GLASS RH (WCP)  | BROKEN               | 880.00                    | 375.00            |
| 1   | SIDE MIRROR LOWER COVE RH (WCP)   | CUT                  | 55.00                     | 55.00             |
| 1   | FRONT FENDER RH (WCP)   | DENTED               | 450.00                    | 450.00            |
| 1   | FRONT FENDER CHROME RH (WCP)  | NECESSARY            | 35.00                     | 35.00             |
| 1   | FRONT DOOR RH (NPA)   | TO REPAIR SEE LABOUR | -                         | -                 |
| 1   | FRONT BUMPER (NPA)  | TO REPAIR SEE LABOUR | -                         | -                 |
|   | COST PLUS 15%   |                      | 348.00                    | 272.25            |
|   |   |                      | 2,668.00                  | 2,087.25          |
|   | <b><u>LABOUR</u></b>  |                      |                           |                   |
|   | TO REPAIR FRONT DOOR RH, FRONT BUMPER. TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH AND FRONT BUMPER. |                      | 450.00                    | 300.00            |
|   | TO SPRAY FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH, SIDE MIRROR RH AND AFFECTED AREAS.   |                      | 750.00                    | 500.00            |
|   |   |                      | 1,200.00                  | 800.00            |
| <b>GRAND TOTAL</b>  |   |                      | <b>3,868.00</b>           | <b>2,887.25</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |   |                      |                           | <b>2,300.00</b>   |

Report Ref No. CS/LPC21004401/Evf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.