

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 646P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (CONSISTENT)	DENTED	1,828.60	1,028.00
1	TAILGATE LOGO (CONSISTENT)	NECESSARY	78.00	46.90
1	TAILGATE EMBLEM 'TUCSON' (CONSISTENT)	NECESSARY	89.00	43.60
1	TAILGATE EMBLEM 'TURBO' (CONSISTENT)	NECESSARY	75.00	57.00
1	TAILGATE INNER TRIM BOARD (CONSISTENT)	NOT DAMAGED	366.50	-
1	TAILGATE INNER LOCK (CONSISTENT)	DENTED	198.10	74.60
1	TAILGATE INNER LOCK STICKER (CONSISTENT)	NOT DAMAGED	41.08	-
1	TAILGATE WEATHERSTRIP (CONSISTENT)	TORN	245.00	159.00
1	TAILGATE OUTER GARNISH (CONSISTENT)	BROKEN	202.00	202.00
1	TAILGATE OUTER CHROME MOULDING (CONSISTENT)	NOT NECESSARY	117.40	-
1	TAILGATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	198.00	120.00
1	REAR BUMPER (CONSISTENT)	BROKEN	894.00	446.00
1	REAR BUMPER LOWER (CONSISTENT)	BROKEN	420.00	358.50
1	REAR BUMPER OUTER TOP GARNISH (CONSISTENT)	NOT DAMAGED	185.90	-
2	REAR BUMPER SIDE RETAINER @\$89.00 (CONSISTENT)	NECESSARY	178.00	100.00
1	REAR BUMPER INNER SPONGE (CONSISTENT)	NO SUCH PARTS	118.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BROKEN	359.90	359.90
2	REAR BUMPER BRACKET @\$68.00 (CONSISTENT)	NECESSARY	136.00	76.00
1	REAR BUMPER TOW CAP (CONSISTENT)	DISLODGE	84.00	25.00
2	REAR BUMPER REFLECTOR @\$146.70 (CONSISTENT)	O/S BROKEN	293.40	128.00
4	REAR BUMPER REVERSE SENSOR @\$280.00 (CONSISTENT)	SCRATCHED (2 PCS ONLY)	1,120.00	320.00
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	985.60	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT DAMAGED	117.80	-
	LESS 20% DISCOUNT		-1,666.26	-708.90
			6,665.02	2,835.60
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	80.00	_
1	TAILGATE SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	40.00

Report Ref No. CC4/ASM21004405/Bps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	TAILGATE INNER TRIM BOARD CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	TAILGATE OUTER GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	20.00
1	TAILGATE WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	60.00
1	TAILGATE WINDSCREEN INNER SEAL (SN) (CONSISTENT)	NO SUCH PARTS	60.00	-
1	TAILGATE WINDSCREEN PRIMER AND CLEANER (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	REAR BUMPER LOWER CLIPS (SN) (CONSISTENT)	NO SUCH PARTS	50.00	-
1	REAR BUMPER OUTER TOP GARNISH CLIPS (SN) (CONSISTENT)	NO SUCH PARTS	50.00	-
4	REAR BUMPER REVERSE SENSOR SEAL @\$48.00 (SN) (CONSISTENT)	NECESSARY (2 PCS ONLY)	192.00	96.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR NUMBER PLATE W/CASING (SN) (CONSISTENT)	BROKEN	80.00	50.00
			1,092.00	326.00
	<u>LABOUR</u>			
	R&R TAILGATE COMPONENT.		150.00	80.00
	R&R TAILGATE WINDSCREEN .		250.00	120.00
	CHECK WIRING .		100.00	30.00
	DIAGNOSTIC RESET FAULT CODE.	NOT NECESSARY	300.00	-
	UPHOLSTERY.	NOT NECESSARY	300.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,400.00	800.00
	RUST PROOFING .	NOT NECESSARY	200.00	-
	SPRAY PAINTING .		1,400.00	800.00
			4,100.00	1,830.00
	GRAND TOTAL		11,857.02	4,991.60



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS	4,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM21004405/Bps3q2

LIM TEOW GUAN

Automotive Assessor

Amnonto

HO LEONG CHUAN

Automotive Assessor