

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21004412/R1QF3E2

Date: 08/06/2021

REFERENCE

Insured/Claimant: UNIFIED OFFSHORE
ENGINEERING PTE. LTD.

Policy No: DMCVSNW00003852103

Date of Loss: 01/04/2021

Nature of
Claim: OD

Claim
No: SNM21D201942/C01/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF6171U**

Make & Model: TOYOTA DYNA 150 D, 3.0 D (M)

Engine No: 1KD2676578

Reg. Date: 13/01/2017 (Man. Year: 2016)

Chassis No: JTFAT35Y60K207371

Colour: Grey

Odometer: 0 km

Engine Capacity: 2982 cc

Market Value/New Car Price: S\$56,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 155 R12C (D)

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 5/5 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 44,031.42 | 39,971.42 | 4,060.00 | 9.22 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,153.30 | 5,299.68 | -2,146.38 | -68.07 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 47,184.72 | 45,271.10 | 1,913.62 | 4.06 |
| Approved Total (Overridden) (S\$) | | 29,000.00 | | |
| - Excess (S\$) | 0.00 | 500.00 | -500.00 | |
| (S\$) | 47,184.72 | 28,500.00 | 18,684.72 | 39.60 |
| + GST 7.00/7.00% (S\$) | 3,302.93 | 1,995.00 | 1,307.93 | 39.60 |
| Nett Amount (S\$) | 50,487.65 | 30,495.00 | 19,992.65 | 39.60 |

INSPECTION

Date of Assignment: 07/04/2021

Date Inspected: 08/04/2021 Inspected At:

BLK K Pandan Loop Ind Estate #01-12
Repairer: Goldbell Engineering Pte Ltd

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 08 Jun 2021) | |
| Parts: | N/A | TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBF6171U) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---------------------------|-----|----------|---|---------------|------------------|------------------|
| 1 | 1 | | *TOTAL PARTS | | 41,063.42 F | *37,633.42 F |
| Supplementary #1 | | | | | | |
| 2 | 1 | | *CHASSIS MOUNTING BRACKET LH | Not Necessary | 380.00 F | *- F |
| 3 | 1 | | *CHASSIS MOUNTING BRACKET RH | Not Necessary | 380.00 F | *- F |
| 4 | 1 | | *RADIATOR FAN | Cut | 85.00 F | *85.00 F |
| 5 | 1 | | *RADIATOR FAN COWLING | Cracked | 95.00 F | *95.00 F |
| 6 | 1 | | *RADIATOR | Bent | 730.00 F | *730.00 F |
| 7 | 1 | | *RADIATOR FAN CLUTCH | Jammed | 210.00 F | *210.00 F |
| 8 | 1 | | *A/C AIR DAMPER | Necessary | 85.00 F | *85.00 F |
| 9 | 1 | | *CABIN CONTROL ROD | Bent | 438.00 F | *438.00 F |
| 10 | 1 | | *CROSSMEMBER | Bent | 320.00 F | *450.00 F |
| 11 | 1 | | *COOLANT | Necessary | 55.00 F | *55.00 FS |
| 12 | 1 | | *CABIN MOUNTING CUSHION CAB FR MTG ,RH | Deformed | 95.00 F | *95.00 F |
| 13 | 1 | | *CABIN MOUNTING CUSHION CAB FR MTG ,LH | Deformed | 95.00 F | *95.00 F |
| Total Parts (\$\$) | | | | | 44,031.42 | 39,971.42 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|----------------------|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TOTAL LABOUR | New | 1,293.60 | 2,969.40 |
| 2 | TOTAL PAINT (NPA) | New | - | 0.00 |
| 3 | TOTAL PAINT | New | 1,589.70 | 2,100.28 |
| 4 | ADDITIONAL COST | New | 270.00 | 230.00 |
| Gross Labour Cost (S\$) | | | 3,153.30 | 5,299.68 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >