

(08/11/13) wef

ASS. REG. BY: PRANREF: CSCS4/CT121004412/R19/3C
5020**ASSIGNMENT**From: _____ Date: _____
Estimated Cost: _____OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBF 617Mat Workshop m/s: GOLDBELLof BK K PANDAN LAMP IND ESTATE #01-12Insured: CTIPolicy No. DMCVSNW00003852103Claims No. SNM21D201942Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 56K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF 617M Yr Regn: 2017 JAN
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA DYNA 150 SMT c.c. 2982Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 1 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35460K207371Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15CR: 155R12CSS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 5/5 mmL/Bal. 7 mm L/Bal. 5/5 mmD.O.A. 01/04/21 D.O.I. 08/04/21Survey held at GOLDBELLDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 29K

09/04/21@5.47pm revert to Adeline Chng via Merimen.

13/04/21@12.19pm So Chow informed C/A at \$29K via Merimen..

13/04/21@3.51pm Informed Brian C/A not more than LS \$29K & ex:\$500 by email.

31/05/21 Rasul finalised with Brian Ls \$29000, 14 days (Red \$18314.72, 39%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 03/06 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Report Format : MER-ODLump Sum H.B.I. (\$ 29000)

Goldbell Engineering Pte Ltd
8 Tuas Ave 18, Singapore
638892

Insurer Reference: GBF6171U
Repairer Reference: GBF6171U
Date calculated: 08/04/2021 11:07 AM

Full Report
Registration: GBF6171U
Printed: 08/04/2021 11:07 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Catherine Chong Kai Ling	Currency:	SGD
Claim Reference:	GBF6171U	Date of Incident:	01/04/21
Estimated Repair Time:	25	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	DYNA
Sub Model:	150
Model Sheet Number:	70 1N 03
Registration:	GBF6171U
VIN number:	
Odometer:	0

Model Specs

FROM 10.2016	AIR CONDITIONING	SINGLE CAB	3.0 LTR 80KW
DRIVER AIRBAG	TWO COAT METALLIC	PREPARE OFF VEHICLE	


Vehicle Condition

Vehicle Status

Pre-Accident Damage:	*BATTERY FLAT
Date of Inspection:	

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

Code	Description	WU	Price SGD
NO NUMBER	R + R DUMPING LINKAGE	9.0	37.80
NO NUMBER	RENEW L/F CAB BRACKET	5.0	21.00
NO NUMBER	RENEW R/F CAB BRACKET	5.0	21.00
NO NUMBER	R + R CAB	30.0	126.00
NO NUMBER	R + R L/CAB LOCK	4.0	16.80
NO NUMBER	R + R CAB BRACKET	8.0	33.60
NO NUMBER	R + R UPPER FRONT PANEL	6.0	25.20
	INCLUDES: R + R UPPER END PANELS, WIPER ARMS AND MOULDING		
NO NUMBER	R + R BADGE "DYNA"	2.0	8.40
NO NUMBER	REMOVE AND REFIT L/OUTER WHEELHOUSE	2.0	8.40
520011)	R + R FRONT BUMPER	4.0	16.80
520011)	RENEW FRONT BUMPER (REMOVED)	2.0	8.40
751011	R + R RADIATOR GRILLE	3.0	12.60
810121Y)	R + R LEFT HEADLAMP	1.0	4.20
	(RADIATOR GRILLE REMOVED)		
810121Y)	R + R RIGHT HEADLAMP	1.0	4.20
	(RADIATOR GRILLE REMOVED)		
810151A	ADJUST HEADLAMPS	3.0	12.60
NO NUMBER	R + R L/F LOWER CLOSING PANEL	1.0	4.20
NO NUMBER	R + R R/F LOWER CLOSING PANEL	1.0	4.20
NO NUMBER	RENEW FRONT NUMBER PLATE (REMOVED)	1.0	4.20
851061)	R + R FRONT WASHER NOZZLE/S	1.0	4.20
554051)	R + R REAR SCREEN	6.0	25.20
NO NUMBER	R + R L/F STEP	3.0	12.60
752051	R + R LEFT MIRROR	4.0	16.80
NO NUMBER	R + R L/B-PILLAR BADGE	2.0	8.40
NO NUMBER	R + R R/F STEP BOARD	3.0	12.60
752051	R + R RIGHT MIRROR	4.0	16.80
NO NUMBER	R + R R/B-PILLAR BADGE	2.0	8.40
NO NUMBER	RENEW FRONT CROSSMEMBER	25.0	105.00
NO NUMBER	R + R R/F SEAT BELT BUCKLE	1.0	4.20
NO NUMBER	R + R CENTRE BUCKLE ANCHORAGE (CTR ROW)	1.0	4.20
743201)	R + R HEADLINING	5.0	21.00
	INCLUDES: R + R INSIDE MIRROR, PILLAR TRIMS AND SEAT BELTS		
NO NUMBER	R + R L/F LOWER DOOR SEAL	2.0	8.40
NO NUMBER	R + R R/F LOWER DOOR SEAL	2.0	8.40
711501	R + R CENTRE SEAT BELT	3.0	12.60
711041 ZAX	R + R L/SEAT	2.0	8.40
711041 ZAX	R + R R/SEAT	2.0	8.40
743521)	R + R REAR FLOOR CARPET	6.0	25.20
870031)	R + R HEATING CPL	12.0	50.40
870151N	R + R BLOWER (HEATER REMOVED)	16.0	67.20
550451)	R + R INSTRUMENT PANEL	9.0	37.80
550451)	RENEW INSTRUMENT PANEL (REMOVED)	4.0	16.80
NO NUMBER	R + R INSTRUMENT PANEL CARRIER (REMOVED)	2.0	8.40
850161)	R + R WIPER MOTOR (WIPER UNIT REMOVED)	1.0	4.20
850171)	R + R WIPER LINKAGE	1.0	4.20
862051	R + R COMPRESSOR FANFARE	2.0	8.40
441101	R + R STEERING WHEEL	2.0	8.40
002889 ZAX	DRAIN AND REFILL AIR CONDITIONING	7.0	29.40
1002	CABIN HEAD CABIN HEAD	300.0*	1,260.00
1007	R/I SEAT SEAT	40.0*	168.00

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	55.80	558.0	2,343.60
Total of Labour			2,343.60

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	L/R CORNER PILLAR NEW PART PAINTING	13.0
	R/R CORNER PILLAR NEW PART PAINTING	13.0
	GRILLE NEW PART PAINT K1G/P	8.0
	OUTER BODY CPL REPAIR PAINTING >50%	234.0

Paint Material Per Part

Code	Description	Price SGD
2103	L/R CORNER PILLAR NEW PART PAINTING	11.00
2104	R/R CORNER PILLAR NEW PART PAINTING	11.00
0411	GRILLE NEW PART PAINT K1G/P	21.60
0221	OUTER BODY CPL REPAIR PAINTING >50%	240.60

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		268.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	10 WU/h	301.0	1,264.20

Material Cost - Paint

	Price SGD
New Part Painting	22.00
New Part Painting - Plastic K1G/PUR	21.60
Repair Painting	240.60
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	325.50

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
0257	bt/ FRONT NUMBER PLATE	KNPL3	Original		25.00
0281	bt/ FRONT BUMPER	52101 37985	Original		360.00
0293	bt/ L/F BUMPER BRACKET	52012 37070	Original		165.00
0294	bt/ R/F BUMPER BRACKET	52011 37070	Original		165.00
0411	cm/ GRILLE	53111 37A01A0	Original		256.00
0481	nu/ BADGE	75315 37080	Original		95.00
0484	nu/ BADGE MODEL	75311 25100	Original		85.00
0489	nu/ L/F BADGE	75362 35090	Original		65.00
0490	nu/ R/F BADGE	75362 35090	Original		65.00
0561	su/ LEFT HEADLAMP ASSY	81170 37660	Original		420.00
0562	bu/ RIGHT HEADLAMP ASSY	81130 37660	Original		420.00

Code	Description	Part Number	Part Source	Price SGD
0647	scd/ L/F BUMPER FLAP	81482 37040	Original	95.00
0648	cut/ R/F BUMPER FLAP	81481 37040	Original	95.00
0889	mis/ L/F LOWER END PANEL	53814 37100A0	Original	142.50
0890	mis/ R/F LOWER END PANEL	53813 37100A0	Original	142.50
1436	X ? WASHER RESERVOIR	85315 25050	Original	0.00
1450	X WIPER MOTOR	85070 25120	Original	195.00
1453	bt/ L/FR WIPER ARM	85221 37250	Original	125.00
1454	bt/ R/FR WIPER ARM	85211 37250	Original	125.00
1457	na/ L/F WIPER BLADE	85222 37141	Original	32.50
1458	na/ R/F WIPER BLADE	85212 37081	Original	32.50
1469	? WIPER LINKAGE	85150 37150	Original	120.00
1737	bro/ L/DOOR MIRROR ASSY	87940 37E92	Original	338.00
1738	scd/ R/DOOR MIRROR ASSY	87910 25051	Original	250.00
2083	X REAR SCREEN INN SEAL	64831 37041		0.00
2205	X L/F STEP	51772 37131	Original	185.00
2206	cut/ R/F STEP	51771 25021	Original	185.00
2600	net/ GLOVEBOX	55440 37020C0	Original	1,650.00
2759	bt/ L/F SUPPORT BRACKET	51702 25060	Original	650.00
2760	bt/ R/F SUPPORT BRACKET	51701 25110	Original	650.00
2801	X L/LOCKING CLIP	54990 25011	Original	550.00
2812	? SHIFT LINKAGE	54801 25052	Original	950.00
3010	X FRONT CROSSMEMBER	51211 25100	Original	450.00
3050	X CAB SUPPORT	51705 25052	Original	785.00
3159	X REAR SCREEN BOND KIT	PZ49I 00C1131		0.00
3737	X L/F WASHER JET	85381 37030	Original	45.00
3738	X R/F WASHER JET	85381 37030	Original	45.00
3739	X HORN	86520 25150	Original	65.00
4331	di/ INSTRUMENT PANEL	55301 37090C0	Original	1,714.42
4339	? L/LWR INST PNL COVER	55312 37011B0	Original	395.00
4411	? HEATER CPL	87150 37230	Original	1,800.00
4415	? HEATER BLOWER CPL	87210 37100	Original	1,500.00
4653	X L/SEAT BELT BUCKLE	SEE GUIDE NO. 4661	Original	120.00
4654	X R/SEAT BELT BUCKLE	73230 37220B0	Original	120.00
4655	X CENTRE BELT BUCKLE	73150 37130B0	Original	120.00
4661	ACT/ LEFT SEAT BELT	73210 37252B1	Original	980.00
4662	ACT/ RIGHT SEAT BELT	73210 37210B1	Original	980.00
4663	X CENTRE SEAT BELT	73240 37161B3	Original	980.00
4957	X HEADLINING	63310 37611B0	Original	780.00
7445	ACT/ DRIVER AIRBAG	45130 37140B0	Original	1,500.00
9974	X POWER STEERING OIL	NO NUMBER	Original	50.00
9986	X AIR CON COOLANT	NO NUMBER	Original	0.00
9988	na/ BRAKE FLUID	NO NUMBER	Original	30.00
1000	bt/ CABIN HEAD	CABIN HEAD	Original	21,500.00
1006	? WIPER TANK (1)	WIPER TANK	Original	75.00
1008	cut/ ROUND MIRROR (1)	ROUND MIRROR	Original	45.00

f: OEM Parts

n: Non-OEM Parts

u: Used parts

Savings

Subtotal

Total

0.00

42,713.42

42,713.42

Extras

Code	Description	Price SGD
1001	COM STICKER (1) COM STICKER	40.00*

Code	Description	Price SGD
1003	ALIGNMENT (1) ALIGNMENT	80 120.00*
1004	ERP BRKT (1) ERP BRKT	25.00*
1005	A/C gas (1) A/C gas	85.00*
Total Extras		270.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	42,713.42	42,713.42
Labour Time Base 10 WU/h		
Total 558.0 WU X 42.00 SGD/h	2,343.60	
Total of Labour		2,343.60
Total Of Extras		270.00
Paint Work Time Base 10 WU/h		
Labour Cost 301.0 WU X 42.00 SGD/h	1,264.20	
Material Cost	325.50	
Total Paint Including Material		1,589.70
Repair Cost Excludes GST		46,916.72
GST (+7.0%)		3,284.17
Repair Cost Included GST		50,200.89

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paul
Hp 90010068
14 days / L/S
08/04/21 @ 1145
EXCESS: 500
Repeat
Resurvey after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 06/04/2021 12:31 (SGT)
Date of Accident 01/04/2021 12:00 (SGT)
Exact Location of Accident 627860, 61 Jurong Island Hwy, Singapore 627860
Additional Location Information JURONG ISLAND HIGHWAY
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF6171U

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner UNIFIED OFFSHORE ENGINEERING PTE. LTD.
Company Reg No 2XXXXXX502D
Email Address Unified.jo@gmail.com
Mobile Phone No (Phone) +65-94387647
Alternative Phone No (Office) +65-94387647

VEHICLE PARTICULARS

Manufacturer Toyota
Model Dyna
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Manual
CC 2982

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMCVSNW00003852103
Cover Note Number -

DRIVER

Name of Driver TENG AH TEE
NRIC No SXXXX535Z

Date Of Birth 06/08/1943
 Occupation Outdoor
 Date Of Driving Pass 29/12/1964
 Driving experience 56 YEARS AND 4 MONTHS
 Gender Male
 Mobile Number
 Alt. Phone Number (Phone) +65-94341187
 Email Address -
 Address Unified.jo@gmail.com
 Address complement BLK 23 TEBAN GARDEN RD
 Postcode #10-159
 Is the driver the policyholder? 600023
 If No, Relationship of the Driver with the Insured No
 Does Driver Own Other Vehicles? Employee
 Vehicle Registration Number of Other Vehicle Owned by Driver No
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Jurong East Neighbourhood Police Centre
 Police Station Phone No (Phone) +65-18008999999
 Alt. Police Station Phone No (Fax) +65-66655791
 Police Station Address No. 92 Boon Lay Way Singapore 609962
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO THE POLICE REPORT T/20210403/2069.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Goods vehicle

Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

VAC
Workshop
Condition

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
 - (ii) investigating the accident and/or my claims,
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Witness's Signature
Date & Time

A: 6BF6171U
B: unknown



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

~~PLEASE REFER TO POLICE REPORT AND T-10010102-1001~~

DECLARATION

I declare the foregoing particulars are true in every respect.



Driver's Signature
of driver is not the same as
Date & Time



Witness's Signature
of witness is not the same as
Date & Time



SINGAPORE POLICE FORCE



T/20210403/2069

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

1 of 3
Report No: T/20210403/2069

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/04/2021 15:34		Vide Report No.:		Station Diary No.: 31	
Informant's Particulars					
Name of Informant: TENG AH TEE			Address: APT BLK 23 TEBAN GARDENS ROAD #10-159 SINGAPORE 600023		
ID Type / ID No.: NRIC NO / S2062535Z			Contact No.: Home/Office: Mobile: 94341187		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 77	Date of Birth: 06/08/1943	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/04/2021 12.00	Type of Location: Straight Road
Location: JURONG ISLAND HIGHWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF6171U	Lorry	TOYOTA	DYNA 150 5MT		Seriously Damaged	0