

SKQ3002E. 2014 Nov

BMW 528i 1997cc

WBA5A52090D284828

TP AXA.

Denise.

Front Bumper.	torn	1689	✓
Front Bumper Clips.	Neu	50	✓
Front Bumper Side Holder RH.	Neu	85	✓
Front Bumper Sponge.	Neu	168	+
Front Bumper Logo.	Neu	89	✓
Front Bumper Sensor	Neu	250	+
Headlamp RH.	Neu	2447	+

Panel Beating

~~400~~ 250

Spray Painting.

~~400~~ 250

Wiring.

~~50~~ 30

To remove front bumper sensor

~~100~~ 30

LST: 1913

Len 10%: 1721.70

Labour: 580

Total 2301.70

L/S: 1850

02 Days.

LPK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(1850)