

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004420/T1RS3Q2
Date: 15/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900019101
Claimant Vehicle No :	SGL8010Y	Insured Vehicle No :	SMJ8048D
Date of Loss:	03/04/2021	Nature of Claim:	TP
		Claim No:	0319638523SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL8010Y		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX483000
Reg. Date:	28/09/2006 (Man. Year: 2006)	Chassis No:	MR053HY4204205631
Colour:	Silver	Odometer:	392319 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,354.57	2,643.35	3,711.22	58.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,680.00	1,590.00	48.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,624.57	4,323.35	5,301.22	55.08
Approved Total (Overridden) (S\$)		2,500.00		

(S\$)	9,624.57	2,500.00	7,124.57	74.02
+ GST 7.00/7.00% (S\$)	673.72	175.00	498.72	74.02
Nett Amount (S\$)	10,298.29	2,675.00	7,623.29	74.02
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,482.45		

INSPECTION

Date of Assignment: 07/04/2021

Date Inspected: 07/04/2021

Inspected At:

Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	510.00 FL	*510.00 FL
2	1		*REAR BUMPER SIDE BRACKET	Not Necessary	60.40 FL	*- FL
3	2		*REAR BUMPER RETAINER	Necessary	71.40 FL	*71.40 FL
4	1		*REAR END PANEL	Bent	575.00 FL	*575.00 FL
5	1		*REAR END PANEL TOP GARNISH	Cracked	201.10 FL	*201.10 FL
6	2		*REAR TAILLAMP	Cracked	571.40 FL	*571.40 FL
7	2		*REAR TAILLAMP PANEL	Repair	210.00 FL	*- FL
8	1		*REAR EXHAUST SILENCER	Repair	596.00 FL	*- FL
9	2		*REAR EXHAUST MOUNTING	Not Necessary	80.40 FL	*- FL
10	2		*REAR FENDER LH/RH	Repair	1,410.00 FL	*- FL
11	2		*REAR FENDER INNER TRIM	Not Necessary	450.00 FL	*- FL
12	1		*BOOTLID	Bent	511.00 FL	*511.00 FL
13	1		*BOOTLID WEATHERSTRIP	Cut	175.80 FL	*175.80 FL
14	1		*BOOTLID LOGO	Necessary	48.10 FL	*48.10 FL
15	1		*BOOTLID EMBLEM -VIO	Necessary	45.00 FL	*45.00 FL
16	1		*BOOTLID EMBLEM -E	Necessary	35.00 FL	*35.00 FL
17	1		*BOOTLID EMBLEM -1.5	Necessary	40.00 FL	*40.00 FL
18	1		*BOOTLID EMBLEM -S	Necessary	38.00 FL	*38.00 FL
19	1		*BOOTLID EMBLEM -VVTI	Necessary	180.00 FL	*180.00 FL
20	1		*BOOTLID OUTER GARNISH	Not Necessary	130.00 FL	*- FL
21	1		*BOOTLID LOCK	Bent	96.00 FL	*96.00 FL
22	1		*BOOTLID LOCK STRIKER	Repair	55.00 FL	*- FL
23	2		*BOOTLID HINGE	Repair	110.00 FL	*- FL
24	1		*SPARE TYRE INNER CENTRE SPONGE	Not Necessary	127.00 FL	*- FL
25	2		*SPARE TYRE SIDE SPONGE	Not Necessary	216.00 FL	*- FL
26	1		*SPARE TYRE TOP BOARD	Not Necessary	115.50 FL	*- FL
27	1		*REAR FLOOR PANEL	Repair	668.00 FL	*- FL
28	1		*REAR NUMBER PLATE	Necessary	60.00 FS	*30.00 FS
29	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
30	1		*SET REAR FENDER INNER CLIP	Not Necessary	60.00 FS	*- FS
31	1		*SET REAR END PANEL GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
32	1		*REAR JOINT SEALANT	Necessary	120.00 FS	*40.00 FS
33	1		*SET REAR REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS
34	1		*FLOOR INSULATOR	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (S\$)	8,186.10
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,831.53
					Total Parts (S\$)	6,354.57

3,417.80

774.45

2,643.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK FRONT AND REAR WIRING AND LIGHTING SYSTEM	New	120.00	30.00
2	REMOVE AND REFIT GARNISH ,LINING AND TRIM FOR REPAIR	New	200.00	60.00
3	REMOVE AND RENEW EXHAUST ASSY	New	200.00	0.00
4	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	60.00
5	PANEL BEATING ON AFFECTED PANEL	New	1,200.00	700.00
6	SPRAY PAINTING ON AFFECTED PANEL	New	1,200.00	800.00
7	APPLY ANTI RUST ON AFFECTED PANEL	New	150.00	30.00
Gross Labour Cost (S\$)			3,270.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >