LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004422/GVF3E2

265429 km

Date: 19/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070136022

Claimant Vehicle SDF5560M Insured Vehicle No: SMV1622D

No: SDF5500IVI Insured venicie No: SIVIV 1022D

Date of Loss: 05/04/2021 Nature of Claim: TP Claim No: 5473660109SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDF5560M

 Make & Model:
 BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)
 Engine No:
 A090J364N13B16A

 Reg. Date:
 08/02/2013 (Man. Year: 2012)
 Chassis No:
 WBA3A12090J719560

Colour: White Odometer:

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50RF17 Rear Tyre Size: 225/50RF17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm
Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/04/2021

Garage 13 Pte Ltd (HQ)

Date Inspected: 07/04/2021 Inspected At: 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46

Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$40,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Distorted	0.00 F	*- F
2	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1	*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
4	1	*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
5	1	*REAR BUMPER FASTENER	Cracked	0.00 F	*- F
6	1	*REAR BUMPER REFLECTOR RH	Cracked	0.00 F	*- F
7	2	*REVERSE SENSOR	Shorted	0.00 F	*- F
8	1	*REAR END PANEL	Repair	0.00 F	*- F
9	1	*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
10	1	*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1	*BOOTLID	Repair	0.00 F	*- F
12	1	*BOOTLID EMBLEM	Necessary	0.00 F	*- F
F=Fra	nchise part.		_		
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted du	ring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >