

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21004427/KVF3E2

Date: 04/08/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD Policy No: 0999993598

Date of Loss: 28/03/2021

Nature of Claim: OD

Claim No: 6337606103SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7899B	Engine No:	27492030970746
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)	Chassis No:	WDC2539462F226286
Reg. Date:	23/06/2017 (Man. Year: 2017)	Odometer:	121724 km
Colour:	Metallic Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,484.15	3,968.60	515.55	11.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	480.00	1,500.00	75.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,464.15	4,448.60	2,015.55	31.18
- Excess (S\$)	1,700.00	1,700.00	0.00	0.00
(S\$)	4,764.15	2,748.60	2,015.55	42.31
+ GST 7.00/7.00% (S\$)	333.49	192.40	141.09	42.31
Nett Amount (S\$)	5,097.64	2,941.00	2,156.64	42.31

INSPECTION

Date of Assignment: 07/04/2021

Date Inspected: 07/04/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY - LH (WCP)	Cut	1,850.00 F	*1,850.00 F
2	1		*FRONT BUMPER (WCP)	Buckled / Cut	980.00 F	*980.00 F
3	1		*FRONT BUMPER LOWER LID (WCP)	Distorted	260.00 F	*260.00 F
4	1		*FRONT BUMPER SIDE RETAINER - LH (WCP)	Serviceable	48.00 F	*48.00 F
5	1		*FRONT BUMPER SENSOR (2PCS) (WCP)	Shorted (1Pc Only)	276.00 F	*138.00 F
6	6		*FRONT BUMPER SENSOR SEALS (WCP)	Necessary	48.00 F	*- F
7	1		*FRONT BUMPER CLIPS (15PCS)	Necessary	107.25 FS	*50.00 FS
8	1		*FRONT WHEEL ARCH GARNISH - LH (WCP)	Cut	195.00 F	*195.00 F
9	8		*FRONT WHEEL ARCH GARNISH CLIPS	Necessary	57.20 FS	*40.00 FS
10	1		*FRONT GRILLE (WCP) (SUPPLEMENTARY)	Serviceable	215.00 F	*- F
11	1		*FRONT BUMPER FOG LAMP COVER - LH (WCP) (SUPPLEMENTARY)	Dented	55.00 F	*55.00 F
					Sub Total (S\$)	4,091.45 3,616.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	392.70 352.60
					Total Parts (S\$)	4,484.15 3,968.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	100.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT & STRAIGHTEN LH FRONT FENDER, LH CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	200.00
4	TO PUTTY & SPRAY ON AFFECTED AREAS	New	800.00	200.00
Gross Labour Cost (S\$)			1,980.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >