

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC21004428/T1vf3e2	
	300 BEACH ROAD CONCOURSESING		Date:	12/04/2021		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SGL 883Y	Veh. Inspected		SLM 8039B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/21/21/VP05/024418	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		07/04/2021	
2.	. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI LANCER EX	c.c		1590	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JMYSRCY1AGU006432	Colour		BLUE	
	Odometer	21369 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	YOKOHAMA		6 mm	
	L/H Front Tyre	205/60 R16	YOKOHAMA		6 mm	
	R/H Rear Tyre	205/60 R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	205/60 R16	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.				
5.	5. General Information					
	Accident Date	dent Date 30/03/2021 Inspect Date / Time			07/04/2021 (05:30 PM)	
	Survey held at	GREEN STAR SPRAY PAINTING				
		BLK 3011 BEDOK NORTH AVE 4 #01-2004 BEDOK INDUSTRIAL PARK E SINGAPORE 489977				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21004428/T1vf3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor