

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004430/BPS3Q2
Date: 25/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070170016
Claimant Vehicle No :	SLL2246P	Insured Vehicle No :	SMN8452Z
Date of Loss:	05/04/2021	Nature of Claim:	TP
		Claim No:	8353512956SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL2246P		
Make & Model:	BMW 320I, 2.0 AT D/AB 4DR ABS HID NAV (A)	Engine No:	A9100224N20B20B
Reg. Date:	21/12/2012 (Man. Year: 2012)	Chassis No:	WBA3B16020NP43683
Colour:	White	Odometer:	166940 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,073.58	5,896.42	16,177.16	73.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,690.00	2,610.00	60.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,373.58	7,586.42	18,787.16	71.23
Approved Total (Overridden) (S\$)		6,050.00		

(S\$)	26,373.58	6,050.00	20,323.58	77.06
+ GST 7.00/7.00% (S\$)	1,846.15	423.50	1,422.65	77.06
Nett Amount (S\$)	28,219.73	6,473.50	21,746.23	77.06
+ Car Rental (7.0 x S\$140.00/day + 7.00% GST) (S\$)		1,048.60		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		180.00		
Nett Liability (S\$)		7,738.55		
Global Sum Settlement (S\$)		7,730.00		

INSPECTION

Date of Assignment: 07/04/2021

Date Inspected: 07/04/2021

Estimated Period of Repair: 6.0 days

Inspected At:

160 SIN MING DRIVE #01-14

Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,340.00 FL	*1,642.00 FL
2	1		*BOOTLID LOGO	Necessary	98.00 FL	*49.85 FL
3	1		*BOOTLID EMBLEM 320I	Necessary	118.00 FL	*75.50 FL
4	1		*BOOTLID LAMP	O/S Broken	1,392.00 FL	*486.90 FL
5	1		*BOOTLID WEATHERSTRIP	Not Damaged	254.00 FL	*- FL
6	1		*BOOTLID INNER LOCK	Not Damaged	568.00 FL	*- FL
7	1		*BOOTLID INNER LOCK STRIKER	Not Damaged	88.00 FL	*- FL
8	1		*BOOTLID INNER TRIM BOARD	Not Damaged	475.00 FL	*- FL
9	1		*REAR BUMPER	Broken	1,740.00 FL	*1,045.45 FL
10	1		*REAR BUMPER LOWER	Broken	786.00 FL	*320.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Necessary	366.80 FL	*111.60 FL
12	1		*REAR BUMPER REINFORCEMENT	Not Damaged	698.00 FL	*- FL
13	2		*REAR BUMPER REINFORCEMENT BRACKET	No such part	396.40 FL	*- FL
14	2		*REAR BUMPER REFLECTOR	Broken	296.00 FL	*72.00 FL
15	1		*REAR BUMPER BEAM	Broken	285.00 FL	*105.80 FL
16	1		*REAR BUMPER BEAM GARNISH	Not Damaged	197.00 FL	*- FL
17	1		*REAR BUMPER UNDER COVER CENTER	Broken	453.00 FL	*155.40 FL
18	1		*REAR BUMPER TOW COVER	Cut	75.00 FL	*17.00 FL
19	4		*REAR BUMPER REVERSE SENSOR	Scratched	1,280.00 FL	*1,000.00 FL
20	1		*REAR END PANEL	Not Damaged	1,120.60 FL	*- FL
21	1		*REAR END PANEL TOP GARNISH	Not Damaged	268.80 FL	*- FL
22	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	1,870.00 FL	*- FL
23	1		*SPARE TYRE PANEL	Not Damaged	1,292.60 FL	*- FL
24	1		*SPARE TYRE PANEL TOP BOARD	Not Damaged	879.00 FL	*- FL
25	2		*TAIL LAMP	Broken	2,377.00 FL	*1,144.00 FL
26	2		*TAIL LAMP LOWER BRACKET	No such part	220.00 FL	*- FL
27	1		*EXHAUST PIPE	Not Necessary	1,807.00 FL	*- FL
28	1		*EXHAUST PIPE MOUNTING	Bent	105.00 FL	*45.00 FL
29	1		*EXHAUST PIPE HEAT SHIELD	Dented	288.00 FL	*105.00 FL
30	1		*REAR BUMPER UNDER COVER RH	Missing	212.00 FL	*54.30 FL
31	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
32	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
33	2		*BOOTLID LAMP SEAL	Not Necessary	120.00 FS	*- FS
34	2		*BOOTLID LAMP CLIPS	Not Necessary	100.00 FS	*- FS
35	1		*BOOTLID INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
37	1		*REAR BUMPER LOWER CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*REAR BUMPER UNDER COVER CENTER CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*REAR BUMPER UNDER COVER RH CLIPS	Not Necessary	50.00 FS	*- FS
40	4		*REAR BUMPER REVERSE SENSOR SEAL	Necessary	232.00 FS	*49.60 FS
41	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
42	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*SPARE TYRE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
45	2		*TAIL LAMP CLIPS	No such part	100.00 FS	*- FS
46	2		*TAIL LAMP SEAL	No such part	120.00 FS	*- FS
47	1		*REVERSE CAMERA	Not Damaged	480.00 FS	*- FS
48	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,308.20	6,539.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,234.62	642.98
Total Parts (\$\$)	22,073.58	5,896.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R BOOTLID COMPONENT	New	150.00	80.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	R&R REVERSE CAMERA	New	100.00	0.00
4	R&R EXHAUST PIPE	New	250.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
7	CHECK WIRING	New	100.00	30.00
8	PANEL BEATING	New	1,400.00	800.00
9	RUST PROOFING	New	200.00	0.00
10	SPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (S\$)			4,300.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >