

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21004436/KGS3Q2  
**Date:** 18/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993826
<b>Claimant Vehicle No :</b>	SLT1444Z	<b>Insured Vehicle No :</b>	SKH3172U
Date of Loss:	06/04/2021	Nature of Claim:	TP
		Claim No:	7649252098SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLT1444Z</b>	Engine No:	2ZRR932743
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	ZVW506048674
Reg. Date:	19/10/2017 (Man. Year: 2016)	Odometer:	310020 km
Colour:	Metallic Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	SUNWIDE 8 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	SUNWIDE 8 mm	Rear Right Side:	West Lake 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,315.00	7,582.49	4,732.51	38.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	2,620.00	1,800.00	40.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,735.00</b>	<b>10,202.49</b>	<b>6,532.51</b>	<b>39.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,150.00</b>		

## Adjuster Report

	(S\$)	16,735.00	8,150.00	8,585.00	51.30
<b>+ GST 7.00/7.00% (S\$)</b>		1,171.45	570.50	600.95	51.30
<b>Nett Amount (S\$)</b>		<b>17,906.45</b>	<b>8,720.50</b>	<b>9,185.95</b>	<b>51.30</b>
<b>+ Car Rental (9.0 x S\$120.00/day) (S\$)</b>			1,080.00		
	(S\$)		9,800.50		
<b>Liabe Amount (50.00%) (S\$)</b>			<b>4,900.25</b>		
<b>+ Doc/Search Fee (S\$)</b>			7.45		
<b>Nett Liability (S\$)</b>			<b>4,907.70</b>		

INSPECTION

Date of Assignment: 07/04/2021

Date Inspected: 07/04/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Optima Werkz Pte Ltd (HQ)  
6 Kung Chong Road  
Singapore 159143

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	616.00 FL	*450.80 FL
2	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	82.00 FL	*82.00 FL
3	1		*FRONT HEADLAMP RH	Mtg Cracked	2,637.00 FL	*2,531.60 FL
4	1		*FRONT FENDER RH	Repair	877.00 FL	*- FL
5	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	55.00 FL	*55.00 FL
6	1		*FRONT FENDER INNER LINER RH	Serviceable	202.00 FL	*- FL
7	1		*FRONT PILLAR GARNISH COVER RH	Serviceable	88.00 FL	*- FL
8	1		*FRONT SIDE MIRROR ASSEMBLY RH	Cracked	1,173.00 FL	*1,023.00 FL
9	1		*FRONT SIDE MIRROR COVER RH	Repair	90.00 FL	*- FL
10	1		*SIDE SKIRT RH	Mtg Cracked	594.00 FL	*594.00 FL
11	1		*FRONT DOOR RH	Dented / Warped	1,249.00 FL	*1,126.60 FL
12	1		*FRONT DOOR FRAME RUBBER RH	Serviceable	223.00 FL	*- FL
13	1		*FRONT DOOR HANDLE RH	Serviceable	378.00 FL	*- FL
14	1		*FRONT RIM RH	Dented	1,555.00 FL	*1,508.10 FL
15	1		*FRONT ABSORBER RH	Serviceable	472.00 FL	*- FL
16	1		*FRONT KNUCKLE ARM RH	Bent	555.00 FL	*360.70 FL
17	1		*FRONT WHEEL BEARING RH	Necessary	554.00 FL	*410.60 FL
18	1		*FRONT CONTROL ARM RH	Serviceable	631.00 FL	*- FL
19	1		*FRONT TIE ROD END RH	Distorted	155.00 FL	*155.00 FL
20	1		*REAR DOOR RH	Bent / Warped	1,243.00 FL	*1,181.75 FL
21	1		*REAR DOOR FRAME RUBBER RH	Serviceable	175.00 FL	*- FL
22	1		*REAR DOOR HANDLE RH	Serviceable	278.00 FL	*- FL
23	1		*REAR FENDER RH	Repair	900.00 FL	*- FL
24	1		*REAR FENDER INNER LINER RH	Serviceable	186.00 FL	*- FL
25	1		*REAR BUMPER	Mtg Cracked	542.00 FL	*497.50 FL
26	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	112.00 FL	*- FL
27	1		*REAR TAIL LAMP RH	Serviceable	478.00 FL	*- FL
28	1		*FRONT BONNET (NPA)	Repair	0.00 FL	*- FL
29	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
30	1		*FRONT FENDER INNER LINER CLIPS RH	Not Necessary	30.00 FS	*- FS
31	1		*FRONT DOOR INNER TRIM CLIPS RH	Not Necessary	40.00 FS	*- FS
32	1		*REAR DOOR INNER TRIM CLIPS RH	Not Necessary	40.00 FS	*- FS
33	1		*REAR FENDER INNER LINER CLIPS RH	Not Necessary	30.00 FS	*- FS
34	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST ACCIDENT AREAS & ETC	New	1,600.00	800.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISING MATERIALS AT FRONT BUMPER ,FRONT FENDER RH ,FRONT BONNET ,FRONT DOOR RH ,SIDE SKIRT RH ,REAR DOOR RH ,REAR FENDER RH ,REAR BUMPER & ETC	New	1,800.00	1,400.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC .TO EFFECT REPLACE OF FRONT DOOR RH	New	120.00	60.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC .TO EFFECT REPLACE OF REAR DOOR RH	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX FRONT RIM RH ,FRONT ABSORBER RH ,FRONT CONTROL ARM RH ,FRONT KNUCKLE ARM & ETC	New	250.00	150.00
6	TO WHEEL ALIGNMENT & BALANCING	New	80.00	60.00
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	100.00	30.00
9	TO TUFF KOTE & UNDERSEAL MATERIALS	New	200.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>4,420.00</b>	<b>2,620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >