

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21004438/APA3Q2
Date: 23/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070119634
Claimant Vehicle No :	SML5755E	Insured Vehicle No :	GBE815R
Date of Loss:	06/04/2021	Nature of Claim:	TP
		Claim No:	3443887024SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML5755E		
Make & Model:	MERCEDES-BENZ C180 BLUE EFFICIENCY, 1.6 (A)	Engine No:	27491030065881
Reg. Date:	01/08/2013 (Man. Year: 2013)	Chassis No:	WDD2040312A877699
Colour:	Red	Odometer:	81153 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,550.80	8,186.90	5,363.90	39.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	2,140.00	820.00	27.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,510.80	10,326.90	6,183.90	37.45
Approved Total (Overridden) (S\$)		8,200.00		

Nett Amount (S\$)	16,510.80	8,200.00	8,310.80	50.34
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,627.45		
Global Sum Settlement (S\$)		8,620.00		

INSPECTION

Date of Assignment: 08/04/2021

Date Inspected: 08/04/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Premium Carz Services Pte Ltd (HQ)
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,890.00 FL	*1,350.00 FL
2	10		*REAR BUMPER CLIP	Necessary	90.00 FL	*50.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Necessary	88.00 FL	*88.00 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Necessary	88.00 FL	*88.00 FL
5	1		*REAR BUMPER TOW HOOK COVER	Deformed	68.00 FL	*68.00 FL
6	1		*REAR BUMPER CHROME RH	Necessary	188.00 FL	*188.00 FL
7	1		*REAR BUMPER CHROME LH	Necessary	188.00 FL	*188.00 FL
8	1		*REAR BUMPER CHROME CENTRE	Necessary	268.00 FL	*268.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	775.00 FL	*775.00 FL
10	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	162.00 FL	*- FL
11	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,440.00 FL	*500.00 FL
12	1		*REVERSE SENSOR CABLE	Not Necessary	298.00 FL	*- FL
13	1		*TAIL LAMP RH	Cracked	950.00 FL	*690.00 FL
14	1		*TAIL LAMP LH	Not Necessary	950.00 FL	*- FL
15	1		*TAIL LAMP LOWE BRACKET RH	Cracked	89.00 FL	*89.00 FL
16	1		*TAIL LAMP LOWE BRACKET LH	Cracked	89.00 FL	*89.00 FL
17	1		*BOOT LID	Dented	2,170.00 FL	*2,035.00 FL
18	1		*BOOT LID SWITCH (NPA)	Not Necessary	0.00 FL	*- FL
19	1		*BOOT LID LOCK	Damaged	285.00 FL	*285.00 FL
20	1		*BOOT LID LOCK COVER (NPA)	Not Necessary	0.00 FL	*- FL
21	5		*BOOT LID LOCK COVER CLIP	Not Necessary	45.00 FL	*- FL
22	1		*BOOT LID WEATHERSTRIP	Cut	180.00 FL	*180.00 FL
23	1		*BOOT LID LOWER CATCH	Not Necessary	24.00 FL	*- FL
24	1		*BOOT LID TRIMBOARD	Not Necessary	348.00 FL	*- FL
25	10		*BOOT LID TRIMBOARD CLIP	Not Necessary	90.00 FL	*- FL
26	1		*BOOT LID CHROME	Cut	172.00 FL	*172.00 FL
27	1		*BOOT LID M/B LOGO	Necessary	68.00 FL	*68.00 FL
28	1		*BOOT LID 7G-TRONIC EMBLEM	Necessary	98.00 FL	*98.00 FL
29	1		*BOOT LID C180 EMBLEM	Necessary	85.00 FL	*85.00 FL
30	2		*BOOT LID HINGE	Not Necessary	250.00 FL	*- FL
31	8		*BOOT LID INSULATOR CLIP	Not Necessary	72.00 FL	*- FL
32	2		*REAR LICENSE PLATE LAMP	Not Necessary	76.00 FL	*- FL
33	1		*REAR END PANEL	Dented	1,235.00 FL	*1,235.00 FL
34	1		*REAR END PANEL GARNISH	Cracked	156.00 FL	*156.00 FL
35	1		*REAR END PANEL GARNISH CLIP (7 PCS)	Necessary	63.00 FL	*20.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR FENDER TOP MOULDING RH	Cracked	138.00 FL	*138.00 FL
37	1		*REAR FENDER TOP MOULDING LH	Not Necessary	138.00 FL	*- FL
38	10		*REAR FENDER TOP MOULDING CLIP	Necessary (5 PCS ONLY)	90.00 FL	*20.00 FL
39	1		*REAR FENDER INNER TRIM RH (NPA)	Not Necessary	0.00 FL	*- FL
40	18		*REAR FENDER INNER TRIM CLIP	Not Necessary	162.00 FL	*- FL
41	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
42	1		*SPARE TYRE BOARD	Not Necessary	265.00 FL	*- FL
43	1		*CYCLE & CARRIAGE LOGO	Necessary	68.00 FS	*68.00 FS
44	1		*REAR NUMBER PLATE W/CASING	Not Necessary	70.00 FS	*- FS
45	1		*REVERSE CAMERA	Not Necessary	388.00 FS	*- FS
46	1		*REAR BUMPER LOWER BRACKET	N/S Cracked	196.00 FL	*98.00 FL
47	1		*REAR BUMPER PAD	Not Necessary	445.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,998.00	9,089.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,447.20	902.10
Total Parts (\$)	13,550.80	8,186.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	120.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	1,400.00	900.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,000.00	800.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	90.00	60.00
5	TO RESET HEAD REST SYSTEM	New	350.00	350.00
Gross Labour Cost (\$\$)			2,960.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >