

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Make & Model TOYOTA	Policy Particulars :- 1 D V C /2081 E:	Ref: Date: Code: THIRD PARTY CLAIM Peh. Inspected Coverage (\$) Excess (\$) Assign Date		
Insured Veh. SHB 5973 Policy No. Claim No. TAX/03/21 Assign From HUA YAN Make & Model TOYOTA V	Policy Particulars :- 1 D V C C /2081 E:	Code: THIRD PARTY CLAIM /eh. Inspected Coverage (\$) Excess (\$)	SMR SLL 9508M 0.00	
Insured Veh. SHB 5973 Policy No. Claim No. TAX/03/21 Assign From HUA YAN Make & Model TOYOTA V	D V6 C /2081 E:	THIRD PARTY CLAIM /eh. Inspected Coverage (\$) Excess (\$)	SLL 9508M 0.00	
Insured Veh. SHB 5973 Policy No. Claim No. TAX/03/21 Assign From HUA YAN Make & Model TOYOTA V	D V6 C /2081 E:	/eh. Inspected Coverage (\$) Excess (\$)	SLL 9508M 0.00	
Policy No. Claim No. TAX/03/21 Assign From HUA YAN Make & Model TOYOTA	/2081 E :	Coverage (\$) Excess (\$)	0.00	
Claim No. TAX/03/21 Assign From HUA YAN Make & Model TOYOTA	/2081 E :	Excess (\$)		
Assign From HUA YAN Make & Model TOYOTA	A	(-/	0.00	
Make & Model TOYOTA		Assign Date		
Make & Model TOYOTA	Vehicle Particul		06/04/2021	
	2. Vehicle Particulars & Condition			
Engine No. HIDDEN	/IOS c.	c.c	1496	
Engine No. HIDDEN	Y	ear of Reg.	2017	
Chassis No. MHFB29F	3002007645 C	Colour	GREY	
Odometer 302672 KM	Л S	Steering	IN ORDER	
Brakes IN ORDER	M	Modification	SPORTS RIM	
General GOOD				
3. Conditions of Tyres				
Size	M	/lake	Balance	
R/H Front Tyre 195/50 R1	6 C	CONTINENTAL	5 mm	
L/H Front Tyre 195/50 R1	6 C	CONTINENTAL	5 mm	
R/H Rear Tyre 195/50 R1	6 C	CONTINENTAL	5 mm	
L/H Rear Tyre 195/50 R1	6 C	CONTINENTAL	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date 26/03/202	l In	nspection Date	07/04/2021	
Survey held at BORNEO	MOTORS (S) PTE LTD			
	N CRESCENT RE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
R/H Front Tyre 195/50 R1 L/H Front Tyre 195/50 R1 R/H Rear Tyre 195/50 R1 L/H Rear Tyre 195/50 R1 THE VEHICLE SUSTAINED D. DAMAGES SEE DETAILS. Accident Date 26/03/202 Survey held at BORNEO 2 PANDAN SINGAPO 3. A)THE INSPECTION WAS COBIN ACCORDANCE TO YOUR	M66 CG 66 CG 6 CG 6 CG 6 CG 6 CG 6 CG 6 C	Make CONTINENTAL C	5 mm 5 mm 5 mm 5 mm 07/04/2021	