

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SMW7036B
 MODEL : HONDA SHUTTLE
 DATE OF ACCIDENT : 06.04.21
 TIME OF ACCIDENT : 18:10HRS

| | | | | |
|----|------------------------|---|----------|----------|
| 28 | REAR BUZZER <i>Neu</i> | 1 | \$ 86.10 | \$ 86.10 |
|----|------------------------|---|----------|----------|

6543.80
5235.04
 TOTAL PRICE \$ 10,964.00
 LESS 20% \$ 2,192.80
 SUB TOTAL PRICE \$ 8,771.20

| S/N | DESCRIPTION | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|--|-----|-------------|--------------|
| 1 | REAR NUMBER PLATE <i>Neu</i> | 1 | \$ 80.00 | \$ 80.00 |
| 2 | REAR BUMPER CLIP (SET) <i>Neu</i> | 1 | \$ 80.00 | \$ 80.00 |
| 3 | REAR BUMPER SIDE INNER GARNISH CLIP (SET) <i>Neu</i> | 1 | \$ 60.00 | \$ 60.00 |
| 4 | TAIL GATE OUTER GARNISH CLIP (SET) <i>Neu</i> | 1 | \$ 40.00 | \$ 40.00 |
| 5 | TAIL GATE INNER TRIM CLIP (SET) <i>Neu</i> | 1 | \$ 60.00 | \$ 60.00 |
| 6 | TAIL GATE WINDSCREEN SEALANT <i>3 neu</i> | 1 | \$ 80.00 | \$ 80.00 |
| 7 | TAIL GATE WINDSCREEN INNER SEAL | 1 | \$ 60.00 | \$ 60.00 |
| 8 | TAIL LAMP CLIP (SET) <i>Neu</i> | 1 | \$ 60.00 | \$ 60.00 |
| 9 | REAR FENDER INNER TRIM CLIPS (SET) <i>Neu</i> | 1 | \$ 80.00 | \$ 80.00 |
| 10 | REAR END PANEL INSULATION SEAL <i>Neu</i> | 1 | \$ 150.00 | \$ 150.00 |
| 11 | REAR END PANEL TOP GARNISH CLIP (SET) <i>Neu</i> | 1 | \$ 40.00 | \$ 40.00 |
| 12 | REAR JACK COVER GARNISH CLIP (SET) <i>Neu</i> | 1 | \$ 60.00 | \$ 60.00 |
| 13 | REVERSE SENSOR <i>Damaged</i> | 1 | \$ 220.00 | \$ 220.00 |

490 TOTAL \$ 1,070.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

| S/N | JOB DESCRIPTION | PRICE | ADJUSTED COST |
|-----|--|-------------|---------------|
| 1 | PANEL BEATING, REMOVAL AND REPLACING PARTS | \$ 1,400.00 | <i>800</i> |
| 2 | TO SPRAY PAINT AFFECTED AREA | \$ 1,400.00 | <i>800</i> |
| 3 | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING | \$ 80.00 | <i>50</i> |
| 4 | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING | \$ 80.00 | <i>50</i> |
| 5 | REMOVE AND REFIX VIDEO FOOTAGE | \$ 150.00 | <i>50</i> |
| 6 | REMOVE AND REFIX TAILGATE WINDSCREEN | \$ 120.00 | ✓ |
| 7 | TRANSFER TAILGATE MECHANISM | \$ 80.00 | ✓ |

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SMW7036B
 MODEL : HONDA SHUTTLE
 DATE OF ACCIDENT : 06.04.21
 TIME OF ACCIDENT : 18:10HRS

| | | | |
|--|--|-----------|---|
| | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 280.00 | x |
|--|--|-----------|---|

1950

TOTAL \$ 3,590.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,841.20
 TOTAL LABOUR COST : \$ 3,590.00
 TOTAL REPAIR COST : \$ 13,431.20

Adnan G
 2/s 12/04/21

06 Days ✓

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

total: 7675.04

4/s: Gill ✓

MICHELLE

SERVICE ADVISOR
 MICHELLE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: