

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21004441/AGA3Q2
Date: 17/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800071651
Claimant Vehicle No :	PC82H	Insured Vehicle No :	SMA3150X
Date of Loss:	07/04/2021	Nature of Claim:	TP
		Claim No:	5802075765SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC82H	Engine No:	1KD2569981
Make & Model:	TOYOTA HIACE, 3.0 D GL (A)	Chassis No:	KDH2010184380
Reg. Date:	26/04/2016 (Man. Year: 2015)	Odometer:	113475 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,674.96	2,744.00	2,930.96	51.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,750.00	1,340.00	43.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,764.96	4,494.00	4,270.96	48.73
Approved Total (Overridden) (S\$)		3,500.00		

(S\$)	8,764.96	3,500.00	5,264.96	60.07
+ GST 7.00/7.00% (S\$)	613.55	245.00	368.55	60.07
Nett Amount (S\$)	9,378.51	3,745.00	5,633.51	60.07
+ Loss of Use (6.0 x S\$150.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,652.45		

INSPECTION

Date of Assignment: 08/04/2021

Date Inspected: 08/04/2021

Inspected At: Ryder Auto Pte Ltd (HQ)
2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	845.20 FL	*- FL
2	1		*FRONT BUMPER N/S RETAINER	Not Necessary	181.40 FL	*- FL
3	1		*FRONT N/S DOOR	Dented	2,234.57 FL	*1,680.00 FL
4	1		*FRONT N/S DOOR WEATHERSTRIP	Not Necessary	380.20 FL	*- FL
5	1		*FRONT N/S TYRE RIM CAP	Cut	283.63 FS	*80.00 FS
6	1		*REAR BUMPER	Repair	535.50 FL	*- FL
7	1		*REAR BUMPER N/S RETAINER	Not Necessary	156.20 FL	*- FL
8	1		*REAR N/S SLIDING DOOR	Dented	2,364.70 FL	*1,712.00 FL
9	12		*FRONT BUMPER N/S CLIPS	Not Necessary	30.00 FS	*- FS
10	1		*FRONT N/S B PILLAR (NPA)	Repair	0.00 FL	*- FL
11	1		*FRONT N/S TYRE (NPA)	Not Necessary	0.00 FL	*- FL
12	6		*REAR BUMPER N/S CLIPS	Not Necessary	18.00 FS	*- FS
13	1		*REAR N/S PRIVATE BUS STICKER	Necessary	120.00 FS	*60.00 FS
14	1		*REAR N/S DOOR WEATHERSTRIP (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*REAR N/S DOOR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
16	1		*REAR N/S DOOR WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
17	1		*REAR N/S BODY PANEL (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,349.40	3,592.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,674.44	848.00
Total Parts (\$\$)	5,674.96	2,744.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE DAMAGED PARTS	New	1,000.00	500.00
2	TO SPRAY PAINTING	New	1,400.00	1,100.00
3	TO REMOVE AND REFIT REAR N/S DOOR	New	120.00	0.00
4	TO REMOVE AND REPLACE REAR N/S DOOR (MECHANISM)	New	80.00	0.00
5	TO REMOVE AND REFIT FRONT N/S DOOR	New	100.00	0.00
6	TO REMOVE AND REFIT REAR N/S DOOR WINDSCREEN	New	150.00	80.00
7	TO RESET ELECTRICAL SYSTEM	New	100.00	0.00
8	TO CHECK WIRING	New	80.00	30.00
9	TO RE-SEAL ANTI RUST	New	60.00	40.00
Gross Labour Cost (\$\$)			3,090.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >