

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21004453/KPS3Q2
Date: 12/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900100928
Claimant Vehicle No :	SHB7686U	Insured Vehicle No :	SGL5905K
Date of Loss:	02/04/2021	Nature of Claim:	TP
		Claim No:	4153471225SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7686U	Engine No:	2ZR2C30609
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU703081687
Reg. Date:	27/06/2019 (Man. Year: 2018)	Odometer:	125603 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 7 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,078.73	825.73	3,253.00	79.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,610.00	470.00	9,140.00	95.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,688.73	1,295.73	12,393.00	90.53
+ GST 7.00/7.00% (S\$)	958.21	90.70	867.51	90.53

Nett Amount (S\$)	14,646.94	1,386.43	13,260.51	90.53
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$148.10/day) (S\$)		592.40		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,186.28		
Global Sum Settlement (S\$)		2,185.00		

INSPECTION

Date of Assignment: 06/04/2021

Date Inspected: 06/04/2021

Estimated Period of Repair: 2.0 days

Inspected At:

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63
 SINGAPORE 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled / Dented	442.60 FL	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*COVER ,REAR BUMPER ,LOWER	Dented	15.40 FL	*15.40 FL
4	1		*GUARD ,REAR BUMPER ,CENTER	Bent	576.31 FL	*576.31 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	117.70 FL	*- FL
7	1		*FILLER ,REAR BUMPER EXTENSION ,LH	Serviceable	123.70 FL	*- FL
8	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Serviceable	123.70 FL	*- FL
9	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
10	1		*LENS AND BODY ,REAR LAMP ,RH	Serviceable	502.00 FL	*- FL
11	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Serviceable	451.80 FL	*- FL
12	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Serviceable	925.60 FL	*- FL
13	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
14	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,173.31	1,084.31
- List Item Discount on L Items 25.00/25.00% (\$)	1,094.58	258.58
Total Parts (\$)	4,078.73	825.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	200.00
3	TO TRANSFER OF END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
5	TO REMOVE AND REFIT ELECTRICAL WIRING ,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
6	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	480.00	0.00
7	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT VACUUM AND CHARGE-IN -GAS	New	380.00	0.00
8	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
11	TOWING FEES	New	150.00	0.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	220.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
15	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
17	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
18	TO LIFT-UP /OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
19	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (S\$)			9,610.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >