

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CS/CTI21004454/AVF3Q2

Date:

14/06/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMPCSNW00030562100

Claimant Vehicle No : GBK5969R**Insured Vehicle No :** SKK352X

Date of Loss: 03/04/2021

Nature of Claim: TP

Claim No: SNM21D201992/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBK5969R**

Make & Model: NISSAN NV200, 1.6 (A)

Engine No: HR16164520D

Reg. Date: 18/09/2020 (Man. Year: 2020)

Chassis No: JN1YAAM20Z0001019

Colour: Silver

Odometer: 24207 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/80 R14	Rear Tyre Size:	165/80 R14
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,278.33	4,864.86	2,413.47	33.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,545.00	2,020.00	1,525.00	43.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,823.33	6,884.86	3,938.47	36.39
Approved Total (Overridden) (S\$)		5,500.00		

(S\$)	10,823.33	5,500.00	5,323.33	49.18
+ GST 7.00/7.00% (S\$)	757.63	385.00	372.63	49.18
Nett Amount (S\$)	11,580.96	5,885.00	5,695.96	49.18

INSPECTION

Date of Assignment: 08/04/2021

Date Inspected: 08/04/2021

Estimated Period of Repair: 7.0 days

Inspected At:

SK Automobile Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre
 Singapore 415933

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:		(Last Synchronised: 07 Jun 2021)
Parts:	N/A	NISSAN NV200 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK5969R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	1,835.00 FL	*1,835.00 FL
2	1		*REAR TAILGATE LOGO EMBLEM	Necessary	59.70 FL	*59.70 FL
3	1		*REAR TAILGATE NV200 EMBLEM	Necessary	87.00 FL	*87.00 FL
4	1		*REAR TAILGATE VANTTE EMBLEM	Necessary	69.50 FL	*69.50 FL
5	1		*REAR TAILGATE OUTER GARNISH	Cracked	363.00 FL	*363.00 FL
6	1		*REAR TAILGATE INNER TRIM BOARD	Deformed	180.50 FL	*180.50 FL
7	1		*REAR TAILGATE MECHANISM LOCK	Damaged	261.00 FL	*261.00 FL
8	1		*REAR TAILGATE WEATHERSTRIP	Cut	93.80 FL	*93.80 FL
9	1		*REAR TAILLAMP LH/RH	Not Necessary	258.70 FL	*- FL
10	1		*REAR BUMPER	Deformed	481.10 FL	*481.10 FL
11	2		*REAR BUMPER SIDE RETAINER LH/RH	Necessary	72.60 FL	*72.60 FL
12	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	26.10 FL	*- FL
13	1		*REAR END PANEL OUTER	Dented	162.40 FL	*162.40 FL
14	1		*REAR END PANEL INNER	Dented	644.00 FL	*644.00 FL
15	1		*REAR END PANEL INNER TOP GARNISH	Cracked	83.50 FL	*83.50 FL
16	1		*REAR END PANEL TAILGATE LOCK STRIKER	Not Necessary	47.10 FL	*- FL
17	1		*REAR FLOOR PANEL	Repair	1,228.40 FL	*- FL
18	1		*REAR FLOOR PANEL TOP CARMET	Not Necessary	438.00 FL	*- FL
19	1		*SPARE TYRE BRACKET	Bent	251.10 FL	*251.10 FL
20	1		*SET SPARE TYRE SCREW LOCK	Bent	108.20 FL	*108.20 FL
21	1		*REAR TAILGATE INNER HANDLE	Deformed	35.00 FL	*35.00 FL
22	1		*REAR BUMPER INNER SPONGE	Cracked	118.00 FL	*118.00 FL
23	1		*SET REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Necessary	100.00 FS	*60.00 FS
24	1		*REAR TAILGATE 70KM/H STICKER	Necessary	50.00 FS	*15.00 FS
25	1		*REAR TAILGATE 4 PAX STICKER	Necessary	50.00 FS	*15.00 FS
26	1		*SET REAR TAILGATE NUMBER PLATE WITH CASING	Not Necessary	65.00 FS	*- FS
27	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
29	1		*REAR TAILLAMP CLIPS SET LH/RH	Not Necessary	40.00 FS	*- FS
30	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
31	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
32	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
33	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
34	1		*REAR FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,968.70	5,355.40
- List Item Discount on L Items 10.00/10.00% (\$)	690.37	490.54
Total Parts (\$)	7,278.33	4,864.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	2,000.00	1,200.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,000.00	600.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	125.00	80.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REPLACE REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	80.00	50.00
6	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	180.00	60.00
7	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
Gross Labour Cost (S\$)			3,545.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >